Full Reserve Study Rolling Hills CDD Green Cove Springs, Florida



Prepared for FY 2021 Report Date: March 26, 2021





March 26, 2021

Mr. Jim Oliver, District Manager Governmental Management Services, LLC 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Rolling Hills CDD

Dear Mr. Oliver:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by Community Associations Institute (CAI) and the Standards of Practice establish by the Association of Professional Reserve Analysts (APRA). Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

CRShapparl

Charles R. Sheppard *RS PRA CCI* Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275 www.communityadvisors.comm





TABLE OF CONTENTS

EXECUTIVE SUMMARY

Executive Summary	
Current Funding Projection	
Current Funding Plan vs Fully Funded Plan	
FUNDING PLAN	
Recommended Funding Model Projection	
Recommended Funding Plan VS Fully Funded	
CASH FLOW	
Income & Expense Spreadsheet	
EXPENDITURE DETAIL	
Annual Expenditure Detail	
Annual Expenditure Chart	
Asset Current Cost by Category	
COMPONENT INVENTORY	
Component Inventory	
Component Detail Index	
Component Detail	
DISCLOSURERS & INFORMATION	
Methodology & Information	
Terms of Service	
Definitions	

Report Navigation

- **Executive Summary** provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Cash Flow or Component Funding
 - Funding Goal is the funding plan the Association has or one we recommend
 - Fully Funded Reserve Balance is the 100% balance to begin fully funded
 - Full Funding Contribution is the necessary contribution to maintain full funding for year one. Total is the amount required for year one full funding
 - Current Funding Plan currently used by the District
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength or risk
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- **Cash Flow** is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- Annual Expenditure Detail provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- **Component Detail Index** allows quick access to the detail we have included for each component separated into categories
- **Component Detail** provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

Important Information

Level of Service: Level I Full Reserve Study with a site visit, Level II Update with a site visit or Level III Financial Update with no site visit as defined by the National Reserve Study Standards established by the Community Associations Institute. Component quantity, condition and projected remaining useful life were determined with a visual inspection by the Analyst if a site visit was conducted.

Purpose: This study provides an inventory of major components above a threshold value as determined by the Association that require regular replacement and a plan to fund them.

Basis: Our analysis follows the guidelines for Reserve Studies established by the Association of Professional Reserve Analysts (APRA) and the Community Associations Institute (CAI). Components included in this analysis generally meet the following criteria:

- Component must be owned or maintained by the District
- Component must have a limited life
- Component must have a predictable useful life
- Component must have a replacement cost above a threshold cost

These guidelines limit reserve components to predictable expenses and do not consider large expenses such as stormwater systems or dredging of the stormwater ponds. While their replacement cost and remaining useful life may not be predictable they can be expensive, therefore we recommend consideration for funding.

Useful life and remaining useful life projections are determined by our visual inspection of each component, our experience with similar communities, your historical records and if required vendor evaluation. The District may have experienced some replacement cycles for various components with historical cost therefore this information is considered in our analysis. Each cost and useful life was reviewed and compared to similar project we have completed and adjusted as needed. Components with replacement cost over \$1,000 are typically included.

The various component replacement cycles experienced by the District are driven by the level of quality required by the community, cost of maintenance vs replacement, existing condition, and use. All useful life projections found in this analysis are in the acceptable range for this specific type of community.

Replacement cost for components is driven by local market conditions and available of similar materials. Many components have included repair and refurbishment to extend their useful life and reduce holding cost over time.

Funding Goal: The District may elect for the following goals

- Fully Funded Reserve 100% funding for each component
- Threshold Funded Reserve Annual ending balances are maintained above an adequate or "Threshold" level.

Funding Methods: Reserve analysis typically uses two methods of determining necessary funding levels for component replacement; the Component Method the Cash Flow Method.

• The Component Method provides a reserve contribution amount by estimating the current

replacement cost for each component, subtracting that component's current balance which provides the unfunded balance then dividing that total by the number of remaining years of useful life. Each component's contribution is then total for the annual contribution. This method includes inflation of replacement cost and interest on invested funds and provides the least risk of deferred maintenance or special assessment.

- Another version of the Component Method is referred to as "Straight Line Method" which follows the same calculation as above but does not consider interest on funds or inflation on replacement cost. This method only provides a one-year contribution amount and may result in large changes in annual contribution from year to year.
- The Cash Flow Method or pooled method of reserve funding uses the same calculation as the Component Method to determine full funding but rather than 100% funding this method maintains a minimum year-end balance or percent funded that is acceptable to the Association. While this method requires lower contributions, it does have an increased measure of risk for deferred maintenance or special assessment. Managing that risk can be accomplished by annual updates to address changes in inflation and interest rates and component remaining useful life.
- **Cash Flow Method Models** include the Current Assessment Funding Model (AFM) and the Threshold Funding Model (TFM) among others.
 - The AFM Model illustrates the current funding projections adopted by the District and how these perform over time. This model is also used to develop a funding plan with annual contributions entered for each year which allows a custom funding plan.
 - The TFM maintains minimum annual balances or percent funded which are determined by the Analyst or requested by the District. The year with the lowest ending balance is considered the "Threshold Year" for the total funding plan period. This method does not fully fund reserves and has a higher risk of deferred maintenance or special assessment than full funding requiring annual updates.

Conclusion

There are several factors to consider when determining reserve funding levels that include maintaining the quality and value of the community, the ability of the District to respond to unpredictable component failures and to maintain an acceptable level of risk. Full funding provides the lowest risk of deferred maintenance or special assessment but requires large contributions. We recommend the Threshold Funding Plan which keeps reserve balances above a minimum year end balance that is adequate for the District.

Rolling Hills CDD Green Cove Springs, Florida Executive Summary

January 1, 2007

March 4, 2021

73

Report Date	March 26, 2021
Account Number	1651
Version	1
Budget Year Beginning	October 1, 2021
Budget Year Ending	September 30, 2022
	-

Report Parameters

Inflation	2.50%
Annual Assessment Increase	1.00%
Interest Rate on Reserve Deposit	1.00%

2021 Beginning Balance

GENERAL INFORMATION

٠	Date of Completion:	
---	---------------------	--

- Date of site visit:
- Components Included:
- Current replacement cost:
- Level of Service:
- Funding Method:
- Funding Goal:

\$1,944,722 Level I Reserve Study The Cash Flow Method

Adequate funding with moderate contributions

FINANCIAL INFORMATION

• Fully Funded Reserve Balance:

- Current Funding Plan %:
- Full Funding Surplus/Deficit:
- Full Funding Contribution:
- Total Full Funding Contribution:
- Current Contribution:
- Current Plan Performance:
- Recommend Contribution:

\$1,131,555 0% Deficit of \$1,131,555 \$77,664 \$1,209,219 \$75,000 Inadequate for future component funding \$387,050 provides adequate funding


Threshold Funding Model Summary of Calculations

Required Annual Contribution Average Net Annual Interest Earned Total Annual Allocation to Reserves \$387,050.10 <u>\$3,647.64</u> \$390,697.75

Rolling Hills CDD Current Funding Projection

Beginning Balance: \$0

-	-				Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
2021	1 0 1 1 500	75.000	505	22.206	50.041	1 220 020	10/
2021	1,944,722	75,000	527	22,286	53,241	1,228,039	4%
2022	1,993,340	75,750	1,290	110.000	130,281	1,352,054	10%
2023	2,043,174	76,507	874	119,339	88,324	1,361,268	6%
2024	2,094,253	77,273	1,656		167,252	1,495,478	11%
2025	2,146,610	78,045	2,389	6,402	241,284	1,629,147	15%
2026	2,200,275	78,826	1,402	179,939	141,573	1,595,976	9%
2027	2,255,282	79,614	2,212		223,399	1,749,177	13%
2028	2,311,664	80,410	1,269	176,912	128,165	1,728,400	7%
2029	2,369,455	81,214	2,094		211,474	1,891,360	11%
2030	2,428,692	82,026		965,792	-672,292	1,075,002	
2031	2,489,409	82,847		24,196	-613,641	1,206,529	
2032	2,551,644	83,675		190,213	-720,179	1,174,413	
2033	2,615,435	84,512		195,921	-831,588	1,138,960	
2034	2,680,821	85,357			-746,231	1,306,841	
2035	2,747,842	86,211		106,227	-766,247	1,373,520	
2036	2,816,538	87,073		94,139	-773,314	1,457,988	
2037	2,886,951	87,943		65,628	-750,999	1,577,457	
2038	2,959,125	88,823		708,447	-1,370,624	1,044,780	
2039	3,033,103	89,711			-1,280,913	1,228,796	
2040	3,108,931	90,608			-1,190,304	1,421,360	
2041	3,186,654	91,514		186,703	-1,285,493	1,435,404	
2042	3,266,320	92,429			-1,193,064	1,645,417	
2043	3,347,978	93,354		58,878	-1,158,588	1,804,683	
2044	3,431,678	94,287		79,070	-1,143,371	1,951,696	
2045	3,517,470	95,230		6,121	-1,054,262	2,181,732	
2046	3,605,407	96,182		<i>,</i>	-958,079	2,428,479	
2047	3,695,542	97,144		142,864	-1,003,799	2,539,765	
2048	3,787,930	98,116		223,277	-1,128,960	2,576,335	
2049	3,882,628	99,097		11,580	-1,041,443	2,835,858	
2050	3,979,694	100,088		1,574,714	-2,516,069	1,504,830	
2000	э, ли, тол т	100,000		1,071,711	2,510,007	1,501,050	




Community Advisors Page 1-3 March 26, 2021

Rolling Hills CDD Recommended Funding Model Projection

Beginning Balance: \$0

U	C				Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
2021	1,944,722	387,050	3,648	22,286	368,412	1,228,039	30%
2022	1,993,340	144,586	5,130		518,128	1,352,054	38%
2023	2,043,174	146,032	5,448	119,339	550,268	1,361,268	40%
2024	2,094,253	147,492	6,978		704,738	1,495,478	47%
2025	2,146,610	148,967	8,473	6,402	855,776	1,629,147	53%
2026	2,200,275	150,457	8,263	179,939	834,556	1,595,976	52%
2027	2,255,282	151,961	9,865		996,382	1,749,177	57%
2028	2,311,664	153,481	9,730	176,912	982,680	1,728,400	57%
2029	2,369,455	155,016	11,377		1,149,073	1,891,360	61%
2030	2,428,692	156,566	3,398	965,792	343,246	1,075,002	32%
2031	2,489,409	158,131	4,772	24,196	481,953	1,206,529	40%
2032	2,551,644	159,713	4,515	190,213	455,967	1,174,413	39%
2033	2,615,435	161,310	4,214	195,921	425,570	1,138,960	37%
2034	2,680,821	162,923	5,885		594,378	1,306,841	45%
2035	2,747,842	164,552	6,527	106,227	659,230	1,373,520	48%
2036	2,816,538	166,198	7,313	94,139	738,601	1,457,988	51%
2037	2,886,951	167,860	8,408	65,628	849,241	1,577,457	54%
2038	2,959,125	169,538	3,103	708,447	313,435	1,044,780	30%
2039	3,033,103	171,234	4,847		489,515	1,228,796	40%
2040	3,108,931	172,946	6,625		669,086	1,421,360	47%
2041	3,186,654	174,675	6,571	186,703	663,628	1,435,404	46%
2042	3,266,320	176,422	8,401		848,451	1,645,417	52%
2043	3,347,978	178,186	9,678	58,878	977,437	1,804,683	54%
2044	3,431,678	179,968	10,783	79,070	1,089,119	1,951,696	56%
2045	3,517,470	181,768	12,648	6,121	1,277,414	2,181,732	59%
2046	3,605,407	183,586	14,610		1,475,610	2,428,479	61%
2047	3,695,542	185,422	15,182	142,864	1,533,349	2,539,765	60%
2048	3,787,930	187,276	14,973	223,277	1,512,321	2,576,335	59%
2049	3,882,628	189,148	16,899	11,580	1,706,789	2,835,858	60%
2050	3,979,694	191,040	3,231	1,574,714	326,346	1,504,830	22%



The recommended funding plan provides adequate funding with moderate contributions over time.

Community Advisors Page 2-2 March 26, 2021

	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Beginning Balance Annual Assessment Interest Earned	387,050 3,648	368,412 144,586 5,130	518,128 146,032 5,448	550,268 147,492 6,978	704,738 148,967 8,473	855,776 150,457 8,263	834,556 151,961 9,865	996,382 153,481 9,730	982,680 155,016 11,377	1,149,073 156,566 3,398
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	22,286 1,228,039 30% 368,412	1,352,054 38% 518,128	119,339 1,361,268 40% 550,268	1,495,478 47% 704,738	6,402 1,629,147 53% 855,776	179,939 1,595,976 52% 834,556	1,749,177 57% 996,382	176,912 1,728,400 57% 982,680	1,891,360 61% 1,149,073	965,792 1,075,002 32% 343,246
Description Misc. Site Components Concrete Pavers - Entry Concrete Pavers - Resident's Club										
Mail Box Pedestals Street Signs/Poles Wood Boardwalk Frame/Rails/Deck (not pilings) Misc. Site Components Total:										
Streets & Parking Lots Asphalt Mill/Overlay 1 1/2" - Parking Lot Bradley Creek Parkway - 2 Lift										117,976 250,176
Bradley Creek Pkwy - 1 Lift Connector Street Hidden Meadow Court Holly Green Court										13,701 149,342 34,178
Laurel Springs Drive - 1 Lift Paddle Creek Drive Ridgeview Drive Sandy Point Court										98,778 95,757 15,442
Spring Valley Court Woodbridge Crossing Court Streets & Parking Lots Total:										80,483 24,527 880,358

Description Site Lighting Decorative Light Poles - Amenity Light Poles Shoebox Fixtures - Tennis Courts Site Lighting Total: Fencing Aluminum Fence - Pool Chain Link Fence VC 10 Ft - Tennis Courts Fencing Total: Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi. Refurbishment Allowance - Panity Restrom Statis Refurbishment Allowance - Pool Restroms Pool Pool Restroms Vool Deck - Porch Quing Railings - Porch Wood Deck - Porch Apshalt Shingles - Pavilion Asphalt Shingles - Pavilion Apshalt Shingles - Pavilion Metal Roof - Poink Powilion Metal Roof - Poink Pavilion Metal Roof - Poink Pavilion Metal Roof - Fenis Pavilion Metal Roof - Fenis Pavilion Metal Roof - Fenis Pavilion Statis Metal Roof - Fenis Pavilion Kestier S Club Metal Roof - Fenis Pavilion Fencer Statis Fencer Statis Fenterins Pavilion		2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Decoraive Light Poles - Amenity Light Poles Shoebox Fixtures - Tennis Courts Site Lighting Total: Fencing Aluminum Fence - Pool Chain Link Fence VC 10 Ft - Tennis Courts Fencing Total: Mise. Building Components Aluminum Guters/DS - Resident's Club & Pavi Refurbishment Allowance - Family Restroom 5,230 Refurbishment Allowance - Fitness Locker Roo 23,179 Refurbishment Allowance - Pool Restrooms 40,950 Wingl Railings - Porch 2,034 Wood Deck - Porch 2,034 Mise. Building Components Total: 91,174 Roofing Asphalt Shingles - Pavilion Asphalt Shingles - Pavilion Lobo Metal Roof - Point Pavilion Lobo Pointe Pavilion <td>Description</td> <td></td>	Description										
Light Poles Shoebox Fixtures - Tennis Courts Site Lighting Total: Fencing Aluminum Fence - Pool Chain Link Fence VC 10 Pt - Tennis Courts Fencing Total: Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi Refurbishment Allowance - Family Restroom Striptishment Allowance - Pavilion Restrooms Refurbishment Allowance - Pool Restrooms Ning Railings - Porch Wod Deck - Porch Misc. Building Components Total: Ning Railings - Porch Wod Deck - Porch Q.034 Misc. Resident's Club Metal Roof - Point Stall: Asphalt Shingles - Pavilion Metal Roof - Point Resident's Club Metal Roof - Point Resident's Club Metal Roof - Point Resident's Club Metal Roof - Ponis Pavilion Ketarior Painting Fineric Pavilion Fineric Pavilion Metal Roof - Resident's Club	Site Lighting										
Site Lighting Total: Fencing Aluminum Fence + Pol Chain Link Fence VC 10 Pt - Tennis Courts Fencing Total: Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi. Refurbishment Allowance - Family Restroom 5,230 Refurbishment Allowance - Family Restrooms 5,230 Refurbishment Allowance - Family Restrooms 23,179 Refurbishment Allowance - Pool Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 2,034 Wood Deck - Porch 2,034 Wood Deck - Porch 2,034 Misc. Building Components Total: 91,74 Roofing 4kal Roof - Picnic Pavilion Asphalt Shingles - Resident's Club 4kal Roof - Picnic Pavilion Metal Roof - Pool Resident's Club 4kal Roof - Resident's Club Metal Roof - Resident's Club 4kal Roof - Resident's Club Metal Roof - Resident's Club 4kal Roof - Resident's Club Metal Roof - Resident's Club 4kal Roof - Resident's Club Metal Roof - Resident's Club 4kal Roof - Resident's Club Metal Roof - Resident's Club 4kal											
Fencing Aluminum Fence - Pool Chain Link Fence VC 10 Ft - Tennis Courts											
Aluminum Fence - Pool Chain Link Fence VC 10 Ft - Tennis Courts Fencing Total: Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi Refurbishment Allowance - Frimes Locker Roo. Refurbishment Allowance - Frimes Locker Roo. Refurbishment Allowance - Pool Restrooms Refurbishment Allowance - Pool Restrooms Wood Deck - Porch Wood Deck - Porch Wood Deck - Porch Roofing Asphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Metal Roof - Resident's Club	Site Lighting Total:										
Chain Link Fence VC 10 Ft - Tennis Courts Fencing Total: Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi Refurbishment Allowance - Family Restroom Refurbishment Allowance - Pool Restrooms Refurbishment Allowance - Pool Restrooms Vinyl Railings - Porch Wood Deck - Porch Wood Deck - Porch Roofing Asphalt Shingles - Pavilion Asphalt Shingles - Pavilion Metal Roof - Picnic Pavilion Metal Roof - Picnic Pavilion Metal Roof - Resident's Club Pointer Pavilion											
Fencing Total: Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi Refurbishment Allowance - Family Restroom Refurbishment Allowance - Fritness Locker Roo. Refurbishment Allowance - Pool Restrooms Refurbishment Allowance - Pool Restrooms Misc. Building Components Total: Wood Deck - Porch Wood Deck - Porch Roofing Asphalt Shingles - Pavilion Asphalt Shingles - Pavilion Asphalt Shingles - Pavilion Refurbishment Allowance Refurbishmet Stude Pool Pool Monitor Metal Roof - Picnic Pavilion Asphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Metal Roof - Pool Monitor Metal Roof - Resident's Club Metal Roof - Resident's Club Metal Roof - Tennis Pavilion Roofing Total: Exterior Painting Picnic Pavilion 1,600 Pool Pavilion 5,472 Resident's Club 10,230 Pennis Pavilion 1,600											
Misc. Building Components Aluminum Gutters/DS - Resident's Club & Pavi Refurbishment Allowance - Family Restroom 5,230 Refurbishment Allowance - Family Restrooms 23,179 Refurbishment Allowance - Pool Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 40,950 Wood Deck - Porch 2,034 Wood Deck - Porch 2,034 Nisc. Building Components Total: 91,174 Roofing 40,950 Asphalt Shingles - Pavilion 40,950 Metal Roof - Picnic Pavilion 40,950 Metal Roof - Resident's Club 40,950 Metal Roof - Picnic Pavilion 40,950 Metal Roof - Resident's Club 40,950 Picnic Pavilion 1,600 Pool Pavil											
Aluminum Gutters/DS - Resident's Club & Pavi 5,230 Refurbishment Allowance - Family Restrooms 5,230 Refurbishment Allowance - Finess Locker Roo 23,179 Refurbishment Allowance - Pool Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 40,950 Vinyl Railings - Porch 2,034 Wood Deck - Porch 2,034 Misc. Building Components Total: 91,174 Roofing 3 Asphalt Shingles - Pavilion 4 Asphalt Shingles - Pavilion 4 Metal Roof - Poich Cavilion 91,174 Metal Roof - Poich Cavilion 4 Metal Roof - Resident's Club 4 Roofing Total: 5,472 Pricic Pavilion 5,472 Resident's Club 1,600 </td <td>Fencing Total:</td> <td></td>	Fencing Total:										
Refurbishment Allowance - Family Restroom 5,230 Refurbishment Allowance - Fitness Locker Roo 23,179 Refurbishment Allowance - Pavilion Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 40,950 Vinyl Railings - Porch 2,034 Wood Deck - Porch 2,034 Mise. Building Components Total: 91,174 Roofing 4sphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Hetal Roof - Picnic Pavilion Metal Roof - Picnic Pavilion Hetal Roof - Sesident's Club Metal Roof - Resident's Club Ketarion Metal Roof - Pointing Exterior Painting Picnic Pavilion 1,600 Pool Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion 1,600	Misc. Building Components										
Refurbishment Allowance - Fitness Locker Roo 23,179 Refurbishment Allowance - Pavilion Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 40,950 Wing Railings - Porch 2,034 Wood Deck - Porch 2,034 Misc. Building Components Total: 91,174 Roofing 91,174 Asphalt Shingles - Pavilion 91,174 Metal Roof - Picnic Pavilion 19,780 Metal Roof - Pool Nonitor 19,780 Metal Roof - Resident's Club 19,174 Metal Roof - Pool Nonitor 19,174 Exterior Pavilion 19,174 Resident's Club 19,174 Metal Roof - Pool Nonitor 19,174 Resident's Club 19,174 Metal Roof - Pool Monitor 10,000 Metal Roof - Pool Pavilion 1,600 Pool Pavilion 1,600 Pool Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion 1,600											
Refurbishment Allowance - Pavilion Restrooms 19,780 Refurbishment Allowance - Pool Restrooms 40,950 Vinol Railings - Porch 2,034 Wood Deck - Porch 2,034 Mise. Building Components Total: 91,174 Roofing 91,174 Asphalt Shingles - Pavilion 91,174 Asphalt Shingles - Resident's Club 91,174 Metal Roof - Picnic Pavilion 91,174 Metal Roof - Pool Monitor 91,174 Metal Roof - Pavilion 91,074 Metal Roof - Pavilion 91,074 Metal Roof - Resident's Club 91,0230 Pool Pavilion 1,600 Pool Pavilion 1,600											
Refurbishment Allowance - Pool Restrooms 40,950 Vinyl Railings - Porch 2,034 Wood Deck - Porch 2,034 Misc. Building Components Total: 91,174 Roofing 91,174 Asphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Metal Roof - Picnic Pavilion Ketal Roof - Resident's Club Metal Roof - Resident's Club Ketal Roof - Tennis Pavilion Metal Roof - Tennis Pavilion Ketal Roof - Tennis Pavilion Metal Roof - Resident's Club Ketal Roof - Tennis Pavilion Metal Roof - Resident's Club Ketal Roof - Tennis Pavilion Metal Roof - Resident's Club Ketal Roof - Tennis Pavilion Resident's Club 1,600 Pool Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion 1,600											
Vinyl Railings - Porch 2,034 Wood Deck - Porch 2,034 Misc. Building Components Total: 91,174 Roofing 91,174 Asphalt Shingles - Pavilion 91,174 Asphalt Shingles - Pavilion 91,000 Metal Roof - Picnic Pavilion 91,000 Metal Roof - Pool Monitor 91,000 Metal Roof - Resident's Club 91,000 Roofing Total: 91,000 Exterior Painting 91,000 Picnic Pavilion 9,600 Pool Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion 1,600											
Wood Deck - Porch2,034Mise. Building Components Total:2,034Roofing91,174Asphalt Shingles - Pavilion91,000Asphalt Shingles - Resident's Club4000Metal Roof - Picnic Pavilion4000Metal Roof - Resident's Club4000Metal Roof - Tennis Pavilion4000Exterior Painting4000Picnic Pavilion1,600Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600Pool Pavilion1,600									40,950		
Roofing Asphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Metal Roof - Picnic Pavilion Metal Roof - Pool Monitor Metal Roof - Resident's Club Metal Roof - Resident's Club Metal Roof - Tennis Pavilion Metal Roof - Tennis Pavilion Metal Roof - Tennis Pavilion Pool for Total: Exterior Painting Picnic Pavilion 1,600 Pool Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion 1,600									2,034		
Asphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Metal Roof - Picnic Pavilion Metal Roof - Pool Monitor Metal Roof - Resident's Club Metal Roof - Tennis Pavilion Metal Roof - Tennis Pavilion Roofing Total: Picnic Pavilion Picnic Pavilion Pool Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion 1,600	Misc. Building Components Total:								91,174		
Asphalt Shingles - Pavilion Asphalt Shingles - Resident's Club Metal Roof - Picnic Pavilion Metal Roof - Pool Monitor Metal Roof - Resident's Club Metal Roof - Tennis Pavilion Metal Roof - Tennis Pavilion Roofing Total: Picnic Pavilion Picnic Pavilion Pool Pavilion 5,472 Resident's Club Tennis Pavilion 10,230 Tennis Pavilion	Roofing										
Asphalt Shingles - Resident's Club Metal Roof - Picnic Pavilion Metal Roof - Pool Monitor Metal Roof - Resident's Club Metal Roof - Tennis Pavilion Roofing Total: Exterior Painting Picnic Pavilion Picnic Pavilion 9ol Pavilion 5,472 Resident's Club 10,230 Tennis Pavilion											
Metal Roof - Picnic Pavilion Metal Roof - Pool Monitor Metal Roof - Resident's Club Metal Roof - Tennis Pavilion Roofing Total: Exterior Painting Picnic Pavilion Pool Pavilion 5,472 Resident's Club Tennis Pavilion 10,230 Tennis Pavilion											
Metal Roof - Resident's Club Metal Roof - Tennis PavilionRoofing Total:Exterior PaintingPicnic Pavilion1,600Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600	Metal Roof - Picnic Pavilion										
Metal Roof - Tennis PavilionRoofing Total:Exterior PaintingPicnic Pavilion1,600Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600											
Roofing Total:Exterior PaintingPicnic Pavilion1,600Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600											
Exterior PaintingPicnic Pavilion1,600Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600											
Picnic Pavilion1,600Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600	Kooling lotal:										
Pool Pavilion5,472Resident's Club10,230Tennis Pavilion1,600											
Resident's Club10,230Tennis Pavilion1,600											
Tennis Pavilion 1,600											
,											
	Exterior Painting Total:	18,902									

	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Description										
Flooring										
Carpet - Resident's Club Great Room	1,656									
Carpet - Resident's Club Offices	1,728									
Floor Tile - 1st Floor										
Floor Tile - Lobby										
Rubber Flooring - Fitness Room										
Vinyl Flooring - Kids Zone	2 204									
Flooring Total:	3,384									
Cabinets & Tops										
Top/Sink - Pavilion										
Wood Cabinets & SS Tops - Kitchen								3,530		
Wood Cabinets & SS Tops - Reception/Conf. Rm								6,080		
Cabinets & Tops Total:								9,611		
Furniture Fixtures & Equipment										
Appliance Package - Kitchen					4,305					
Fitness Equip. Full Replace Allowance										
Furniture Allowance - Resident's Club								5,943		
Pool/Deck Furniture Full Replacement Allowan										37,466
Wall Oven Double					2,097					
Furniture Fixtures & Equipment Total:					6,402			5,943		37,466
HVAC Equipment										
Heat Pump 1 - 10 Ton			16,810							
Heat Pump 2 - 8 Ton			13,448							
Heat Pump 3 - 7 Ton			11,767							
HVAC Equipment Total:			42,025							
Swimming Pool										
Concrete Pavers - Pool										
Fiberglass Refurbishment Allow - Pool Slide			15,759							
Lane Divider Reel										
Lane Dividers			3,341							

	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Description										
Swimming Pool continued										
Play Equip. Refurbishment Allow - Splash Pool			5,253							
Pool Filtration Refurbishment Allowance										
Pool Lift								7,608		
Pool Resurfacing/Tile						179,939				
Shade Structure Fabric - Pool			12,607							
Shade Structure Frame - Pool										
Starting Blocks								14,977		
Steel Stair Refurbishment Allowance										
Swimming Pool Total:			36,961			179,939		22,585		
Tennis Courts										
Asphalt Resufacing (color coat)			40,353							47,967
Shade Structure Frame - Tennis Courts										
Tennis Courts Total:			40,353							47,967
Playground										
Park Bench Expanded Metal								2,853		
Plastic Play Surface Border								4,094		
Play Equipment Allowance								35,661		
Swings Two Bay Arched								4,992		
Playground Total:								47,600		
Components Not Included										
Asphalt Seal Coat	Unfunded									
Building Sign	Unfunded									
Ceiling Fans	Unfunded									
Community Signs	Unfunded									
Concrete Curbs/Walks	Unfunded									
Doors/Windows	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Electric Lift	Unfunded									
Fitness Equipment Partial Replace Allowance	Unfunded									
Flag Pole	Unfunded									

	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Description										
Components Not Included continued										
Gas Grill	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Light Poles - Parking Lot	Unfunded									
Monument Sign Refurbishment	Unfunded									
Nets/Poles - Tennis Courts	Unfunded									
Pond Fountains/Aerators	Unfunded									
Pool Filtration Partial Replacement	Unfunded									
Pool/Deck Furniture Partial Replacement	Unfunded									
Railings	Unfunded									
Rubber Play Surface - Playground	Unfunded									
Shade Structure Fabric - Tennis Courts	Unfunded									
Stormwater Pond Dredging/Pipe/Structures	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines	Unfunded									
Volley Ball Court	Unfunded									
Water Cooler - Tennis Courts	Unfunded									
Water Coolers	Unfunded									
=										
Year Total:	22,286		119,339		6,402	179,939		176,912		965,792

	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Beginning Balance Annual Assessment Interest Earned	343,246 158,131 4,772	481,953 159,713 4,515	455,967 161,310 4,214	425,570 162,923 5,885	594,378 164,552 6,527	659,230 166,198 7,313	738,601 167,860 8,408	849,241 169,538 3,103	313,435 171,234 4,847	489,515 172,946 6,625
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	24,196 1,206,529 40% 481,953	190,213 1,174,413 39% 455,967	195,921 1,138,960 37% 425,570	1,306,841 45% 594,378	106,227 1,373,520 48% 659,230	94,139 1,457,988 51% 738,601	65,628 1,577,457 54% 849,241	708,447 1,044,780 30% 313,435	1,228,796 40% 489,515	1,421,360 47% 669,086
Description Misc. Site Components Concrete Payers - Entry			16,784							
Concrete Pavers - Entry Concrete Pavers - Resident's Club Mail Box Pedestals			10,784					12,526		
Street Signs/Poles Wood Boardwalk Frame/Rails/Deck (not pilings)			85,858					31,041		
Misc. Site Components Total: Streets & Parking Lots			102,642					43,567		
Asphalt Mill/Overlay 1 1/2" - Parking Lot Bradley Creek Parkway - 2 Lift Bradley Creek Pkwy - 1 Lift										
Connector Street Hidden Meadow Court										
Holly Green Court Laurel Springs Drive - 1 Lift Paddle Creek Drive										
Ridgeview Drive Sandy Point Court Spring Valley Court										
Woodbridge Crossing Court Streets & Parking Lots Total:										

	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Description										
Site Lighting										
Decorative Light Poles - Amenity		44,086								
Light Poles Shoebox Fixtures - Tennis Courts		85,023								
Site Lighting Total:		129,109								
Fencing										
Aluminum Fence - Pool								38,467		
Chain Link Fence VC 10 Ft - Tennis Courts		61,103								
Fencing Total:		61,103						38,467		
Misc. Building Components										
Aluminum Gutters/DS - Resident's Club & Pavi								4,517		
Refurbishment Allowance - Family Restroom										
Refurbishment Allowance - Fitness Locker Roo										
Refurbishment Allowance - Pavilion Restrooms										
Refurbishment Allowance - Pool Restrooms Vinyl Railings - Porch								4,101		
Wood Deck - Porch								4,101		
Misc. Building Components Total:								8,618		
								0,010		
Roofing								20.045		
Asphalt Shingles - Pavilion								29,945		
Asphalt Shingles - Resident's Club Metal Roof - Picnic Pavilion								70,116 5,365		
Metal Roof - Pool Monitor								2,255		
Metal Roof - Resident's Club								8,474		
Metal Roof - Tennis Pavilion								6,172		
Roofing Total:								122,327		
Exterior Painting										
Picnic Pavilion	2,048									
Pool Pavilion	7,005									
Resident's Club	13,095									
Tennis Pavilion	2,048									
Exterior Painting Total:	24,196									

	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Description										
Flooring										
Carpet - Resident's Club Great Room			2,227							
Carpet - Resident's Club Offices			2,324							
Floor Tile - 1st Floor								7,888		
Floor Tile - Lobby								6,208		
Rubber Flooring - Fitness Room			3,013							
Vinyl Flooring - Kids Zone			5,560							
Flooring Total:			13,123					14,096		
Cabinets & Tops										
Top/Sink - Pavilion			1,345							
Wood Cabinets & SS Tops - Kitchen										
Wood Cabinets & SS Tops - Reception/Conf. Rm										
Cabinets & Tops Total:			1,345							
Furniture Fixtures & Equipment										
Appliance Package - Kitchen							5,790			
Fitness Equip. Full Replace Allowance						36,207				
Furniture Allowance - Resident's Club										
Pool/Deck Furniture Full Replacement Allowan										
Wall Oven Double							2,821			
Furniture Fixtures & Equipment Total:						36,207	8,610			
HVAC Equipment										
Heat Pump 1 - 10 Ton					22,608					
Heat Pump 2 - 8 Ton					18,086					
Heat Pump 3 - 7 Ton					15,825					
HVAC Equipment Total:					56,519					
Swimming Pool										
Concrete Pavers - Pool								235,267		
Fiberglass Refurbishment Allow - Pool Slide					21,195					
Lane Divider Reel								4,108		
Lane Dividers					4,493					

	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Description										
Swimming Pool continued										
Play Equip. Refurbishment Allow - Splash Pool					7,065					
Pool Filtration Refurbishment Allowance						57,932				
Pool Lift										
Pool Resurfacing/Tile								241,998		
Shade Structure Fabric - Pool			15 50 6		16,956					
Shade Structure Frame - Pool			45,726							
Starting Blocks Steel Stair Refurbishment Allowance			20,173							
Swimming Pool Total:			<u> </u>		49,708	57,932		481,373		
			05,900		49,700	51,952		401,373		
Tennis Courts										
Asphalt Resufacing (color coat)							57,018			
Shade Structure Frame - Tennis Courts			12,911							
Tennis Courts Total:			12,911				57,018			
Playground										
Park Bench Expanded Metal										
Plastic Play Surface Border										
Play Equipment Allowance										
Swings Two Bay Arched										
Playground Total:										
Components Not Included										
Asphalt Seal Coat	Unfunded									
Building Sign	Unfunded									
Ceiling Fans	Unfunded									
Community Signs	Unfunded									
Concrete Curbs/Walks	Unfunded									
Doors/Windows	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Electric Lift	Unfunded									
Fitness Equipment Partial Replace Allowance	Unfunded Unfunded									
Flag Pole	Unfunded									

	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Description										
Components Not Included continued										
Gas Grill	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Light Poles - Parking Lot	Unfunded									
Monument Sign Refurbishment	Unfunded									
Nets/Poles - Tennis Courts	Unfunded									
Pond Fountains/Aerators	Unfunded									
Pool Filtration Partial Replacement	Unfunded									
Pool/Deck Furniture Partial Replacement	Unfunded									
Railings	Unfunded									
Rubber Play Surface - Playground	Unfunded									
Shade Structure Fabric - Tennis Courts	Unfunded									
Stormwater Pond Dredging/Pipe/Structures	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines	Unfunded									
Volley Ball Court	Unfunded									
Water Cooler - Tennis Courts	Unfunded									
Water Coolers	Unfunded									
Year Total:	24,196	190,213	195,921		106,227	94,139	65,628	708,447		

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Beginning Balance	669,086	663,628	848,451	977,437	1,089,119	1,277,414	1,475,610	1,533,349	1,512,321	1,706,789
Annual Assessment	174,675	176,422	178,186	179,968	181,768	183,586	185,422	187,276	189,148	191,040
Interest Earned	6,571	8,401	9,678	10,783	12,648	14,610	15,182	14,973	16,899	3,231
Expenditures	186,703		58,878	79,070	6,121		142,864	223,277	11,580	1,574,714
Fully Funded Reserves	1,435,404	1,645,417	1,804,683	1,951,696	2,181,732	2,428,479	2,539,765	2,576,335	2,835,858	1,504,830
Percent Fully Funded	46%	52%	54%	56%	59%	61%	60%	59%	60%	22%
Ending Balance	663,628	848,451	977,437	1,089,119	1,277,414	1,475,610	1,533,349	1,512,321	1,706,789	326,346
Description										
Misc. Site Components										
Concrete Pavers - Entry										
Concrete Pavers - Resident's Club										
Mail Box Pedestals				11,294						
Street Signs/Poles										
Wood Boardwalk Frame/Rails/Deck (not pilings)										
Misc. Site Components Total:				11,294						
Streets & Parking Lots										
Asphalt Mill/Overlay 1 1/2" - Parking Lot										
Bradley Creek Parkway - 2 Lift										409,943
Bradley Creek Pkwy - 1 Lift	72,896									
Connector Street										22,450
Hidden Meadow Court										244,714
Holly Green Court										56,004
Laurel Springs Drive - 1 Lift	82,834									
Paddle Creek Drive										161,859
Ridgeview Drive										156,909
Sandy Point Court										25,303
Spring Valley Court										131,880
Woodbridge Crossing Court	1									40,190
Streets & Parking Lots Total:	155,730									1,249,253

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Description										
Site Lighting										
Decorative Light Poles - Amenity										
Light Poles Shoebox Fixtures - Tennis Courts										
Site Lighting Total:										
Fencing										
Aluminum Fence - Pool										
Chain Link Fence VC 10 Ft - Tennis Courts										
Fencing Total:										
Misc. Building Components										
Aluminum Gutters/DS - Resident's Club & Pavi										
Refurbishment Allowance - Family Restroom								8,570		
Refurbishment Allowance - Fitness Locker Roo Refurbishment Allowance - Pavilion Restrooms								37,982 32,411		
Refurbishment Allowance - Pool Restrooms								67,102		
Vinyl Railings - Porch								- , -		
Wood Deck - Porch								3,333		
Misc. Building Components Total:								149,399		
Roofing										
Asphalt Shingles - Pavilion										
Asphalt Shingles - Resident's Club										
Metal Roof - Picnic Pavilion										
Metal Roof - Pool Monitor Metal Roof - Resident's Club										
Metal Roof - Tennis Pavilion										
Roofing Total:										
Exterior Painting										
Picnic Pavilion	2,622									
Pool Pavilion	8,967									
Resident's Club	16,763									
Tennis Pavilion	2,622									
Exterior Painting Total:	30,973									

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Description										
Flooring										
Carpet - Resident's Club Great Room					2,995					
Carpet - Resident's Club Offices					3,125					
Floor Tile - 1st Floor										
Floor Tile - Lobby										
Rubber Flooring - Fitness Room Vinyl Flooring - Kids Zone										
Flooring Total:					6,121					
					0,121					
Cabinets & Tops										
Top/Sink - Pavilion										
Wood Cabinets & SS Tops - Kitchen								5,785		
Wood Cabinets & SS Tops - Reception/Conf. Rm								9,963		
Cabinets & Tops Total:								15,748		
Furniture Fixtures & Equipment										
Appliance Package - Kitchen									7,786	
Fitness Equip. Full Replace Allowance										
Furniture Allowance - Resident's Club								9,739		
Pool/Deck Furniture Full Replacement Allowan									2 702	
Wall Oven Double								0.720	3,793	
Furniture Fixtures & Equipment Iotai:								9,739	11,580	
HVAC Equipment										
Heat Pump 1 - 10 Ton							30,405			
Heat Pump 2 - 8 Ton							24,324			
Heat Pump 3 - 7 Ton							21,283			
HVAC Equipment Total:							76,012			
Swimming Pool										
Concrete Pavers - Pool										
Fiberglass Refurbishment Allow - Pool Slide							28,504			
Lane Divider Reel										
Lane Dividers							6,043			

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Description										
Swimming Pool continued										
Play Equip. Refurbishment Allow - Splash Pool							9,501			
Pool Filtration Refurbishment Allowance										
Pool Lift								12,466		
Pool Resurfacing/Tile							•• •• •			325,461
Shade Structure Fabric - Pool							22,804			
Shade Structure Frame - Pool								24 5 4 2		
Starting Blocks Steel Stair Refurbishment Allowance								24,542		
Swimming Pool Total:							66,852	37,008		325,461
-							00,052	57,000		525,401
Tennis Courts										
Asphalt Resufacing (color coat)				67,777						
Shade Structure Frame - Tennis Courts										
Tennis Courts Total:				67,777						
Playground										
Park Bench Expanded Metal								4,675		
Plastic Play Surface Border								6,708		
Play Equipment Allowance			51,647					,		
Swings Two Bay Arched			7,231							
Playground Total:			58,878					11,383		
Components Not Included										
Asphalt Seal Coat	Unfunded									
Building Sign	Unfunded									
Ceiling Fans	Unfunded									
Community Signs	Unfunded									
Concrete Curbs/Walks	Unfunded									
Doors/Windows	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Electric Lift	Unfunded									
Fitness Equipment Partial Replace Allowance	Unfunded									
Flag Pole	Unfunded									

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Description										
Components Not Included continued										
Gas Grill	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Light Poles - Parking Lot	Unfunded									
Monument Sign Refurbishment	Unfunded									
Nets/Poles - Tennis Courts	Unfunded									
Pond Fountains/Aerators	Unfunded									
Pool Filtration Partial Replacement	Unfunded									
Pool/Deck Furniture Partial Replacement	Unfunded									
Railings	Unfunded									
Rubber Play Surface - Playground	Unfunded									
Shade Structure Fabric - Tennis Courts	Unfunded									
Stormwater Pond Dredging/Pipe/Structures	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines	Unfunded									
Volley Ball Court	Unfunded									
Water Cooler - Tennis Courts	Unfunded									
Water Coolers	Unfunded									
= Voor Totol	196 702		20 070	70.070	6 1 9 1		117 961	222.277	11 500 1	574 714
Year Total:	186,703		58,878	79,070	6,121		142,864	223,277	11,580 1	,574,714

Description	Expenditures
Replacement Year 2021	
Exterior Painting	
Picnic Pavilion	1,600
Pool Pavilion	5,472
Resident's Club	10,230
Tennis Pavilion	1,600
Flooring	
Carpet - Resident's Club Great Room	1,656
Carpet - Resident's Club Offices	1,728
Total for 2021	\$22,286
	<i> </i>
No Replacement in 2022	
Replacement Year 2023	
HVAC Equipment	
Heat Pump 1 - 10 Ton	16,810
Heat Pump 2 - 8 Ton	13,448
Heat Pump 3 - 7 Ton	11,767
Swimming Pool	
Fiberglass Refurbishment Allow - Pool Slide	15,759
Lane Dividers	3,341
Play Equip. Refurbishment Allow - Splash Pool	5,253
Shade Structure Fabric - Pool	12,607
Tennis Courts	
Asphalt Resufacing (color coat)	40,353
Total for 2023	\$119,339
No Replacement in 2024	
Replacement Year 2025	
Furniture Fixtures & Equipment	
Appliance Package - Kitchen	4,305
Wall Oven Double	2,097
Total for 2025	\$6,402
	φ υ,τυ 2

Description	Expenditures
Replacement Year 2026	
Swimming Pool	
Pool Resurfacing/Tile	179,939
Total for 2026	\$179,939
	<i><i><i>↓,,,,,,,,,,,,,</i></i></i>
No Replacement in 2027	
Replacement Year 2028	
Misc. Building Components	
Refurbishment Allowance - Family Restroom	5,230
Refurbishment Allowance - Fitness Locker Rooms	23,179
Refurbishment Allowance - Pavilion Restrooms	19,780
Refurbishment Allowance - Pool Restrooms	40,950
Wood Deck - Porch	2,034
Cabinets & Tops	
Wood Cabinets & SS Tops - Kitchen	3,530
Wood Cabinets & SS Tops - Reception/Conf. Rm	6,080
Furniture Fixtures & Equipment	
Furniture Allowance - Resident's Club	5,943
Swimming Pool	
Pool Lift	7,608
Starting Blocks	14,977
Playground	
Park Bench Expanded Metal	2,853
Plastic Play Surface Border	4,094
Play Equipment Allowance	35,661
Swings Two Bay Arched	4,992
Total for 2028	\$176,912
No Replacement in 2029	
Replacement Year 2030	
Streets & Parking Lots	
Asphalt Mill/Overlay 1 1/2" - Parking Lot	117,976
Bradley Creek Parkway - 2 Lift	250,176

Description	Expenditures
Replacement Year 2030 continued	
Connector Street	13,701
Hidden Meadow Court	149,342
Holly Green Court	34,178
Paddle Creek Drive	98,778
Ridgeview Drive	95,757
Sandy Point Court	15,442
Spring Valley Court	80,483
Woodbridge Crossing Court	24,527
Furniture Fixtures & Equipment	
Pool/Deck Furniture Full Replacement Allowance	37,466
Tennis Courts	
Asphalt Resufacing (color coat)	47,967
Total for 2030	\$965,792
Replacement Year 2031	
Exterior Painting	
Picnic Pavilion	2,048
Pool Pavilion	7,005
Resident's Club	13,095
Tennis Pavilion	2,048
Total for 2031	\$24,196
Replacement Year 2032	
-	
Site Lighting Decorative Light Poles - Amenity	44,086
Light Poles Shoebox Fixtures - Tennis Courts	85,023
	05,025
Fencing Chain Link Fence VC 10 Ft - Tennis Courts	61,103
Total for 2032	\$190,213
Replacement Year 2033	
Misc. Site Components	
Concrete Pavers - Entry	16,784
Wood Boardwalk Frame/Rails/Deck (not pilings)	85,858

Description	Expenditures
Replacement Year 2033 continued	
Flooring	
Carpet - Resident's Club Great Room	2,227
Carpet - Resident's Club Offices	2,324
Rubber Flooring - Fitness Room	3,013
Vinyl Flooring - Kids Zone	5,560
Cabinets & Tops	
Top/Sink - Pavilion	1,345
Swimming Pool	
Shade Structure Frame - Pool	45,726
Steel Stair Refurbishment Allowance	20,173
Tennis Courts	
Shade Structure Frame - Tennis Courts	12,911
Total for 2033	\$195,921
No Replacement in 2034	
Replacement Year 2035	
HVAC Equipment	
Heat Pump 1 - 10 Ton	22,608
Heat Pump 2 - 8 Ton	18,086
Heat Pump 3 - 7 Ton	15,825
Swimming Pool	
Fiberglass Refurbishment Allow - Pool Slide	21,195
Lane Dividers	4,493
Play Equip. Refurbishment Allow - Splash Pool	7,065
Shade Structure Fabric - Pool	16,956
Total for 2035	\$106,227
Replacement Year 2036	
Furniture Fixtures & Equipment	
Fitness Equip. Full Replace Allowance	36,207
Swimming Pool	
Pool Filtration Refurbishment Allowance	57,932
Total for 2036	\$94,139


Description	Expenditures
Replacement Year 2037	
Furniture Fixtures & Equipment	
Appliance Package - Kitchen	5,790
Wall Oven Double	2,821
Tennis Courts	
Asphalt Resufacing (color coat)	57,018
Total for 2037	\$65,628
Replacement Year 2038	
Misc. Site Components	
Concrete Pavers - Resident's Club	12,526
Street Signs/Poles	31,041
Fencing	
Aluminum Fence - Pool	38,467
Misc. Building Components	
Aluminum Gutters/DS - Resident's Club & Pavilion	4,517
Vinyl Railings - Porch	4,101
Roofing	
Asphalt Shingles - Pavilion	29,945
Asphalt Shingles - Resident's Club	70,116
Metal Roof - Picnic Pavilion	5,365
Metal Roof - Pool Monitor	2,255
Metal Roof - Resident's Club	8,474
Metal Roof - Tennis Pavilion	6,172
Flooring	- 000
Floor Tile - 1st Floor	7,888
Floor Tile - Lobby	6,208
Swimming Pool	225.267
Concrete Pavers - Pool	235,267
Lane Divider Reel Pool Resurfacing/Tile	4,108 241,998
-	
Total for 2038	\$708,447

No Replacement in 2039 No Replacement in 2040

Description	Expenditures
Replacement Year 2041	
Streets & Parking Lots	
Bradley Creek Pkwy - 1 Lift	72,896
Laurel Springs Drive - 1 Lift	82,834
Exterior Painting	
Picnic Pavilion	2,622
Pool Pavilion	8,967
Resident's Club	16,763
Tennis Pavilion	2,622
Total for 2041	\$186,703
No Replacement in 2042	
Replacement Year 2043	
Playground	
Play Equipment Allowance	51,647
Swings Two Bay Arched	7,231
Total for 2043	\$58,878
Replacement Year 2044	
Misc. Site Components	
Mail Box Pedestals	11,294
Tennis Courts	
Asphalt Resufacing (color coat)	67,777
Total for 2044	\$79,070
Replacement Year 2045	
Flooring	
Carpet - Resident's Club Great Room	2,995
Carpet - Resident's Club Offices	3,125
Total for 2045	\$6,121
No Replacement in 2046	
Replacement Year 2047	
HVAC Equipment	
Heat Pump 1 - 10 Ton	30,405


Description	Expenditures
Replacement Year 2047 continued	
Heat Pump 2 - 8 Ton	24,324
Heat Pump 3 - 7 Ton	21,283
Swimming Pool	
Fiberglass Refurbishment Allow - Pool Slide	28,504
Lane Dividers	6,043
Play Equip. Refurbishment Allow - Splash Pool	9,501
Shade Structure Fabric - Pool	22,804
Total for 2047	\$142,864
Replacement Year 2048	
Misc. Building Components	
Refurbishment Allowance - Family Restroom	8,570
Refurbishment Allowance - Fitness Locker Rooms	37,982
Refurbishment Allowance - Pavilion Restrooms	32,411
Refurbishment Allowance - Pool Restrooms	67,102
Wood Deck - Porch	3,333
Cabinets & Tops	
Wood Cabinets & SS Tops - Kitchen	5,785
Wood Cabinets & SS Tops - Reception/Conf. Rm	9,963
Furniture Fixtures & Equipment	
Furniture Allowance - Resident's Club	9,739
Swimming Pool	
Pool Lift	12,466
Starting Blocks	24,542
Playground	
Park Bench Expanded Metal	4,675
Plastic Play Surface Border	6,708
Total for 2048	\$223,277
Replacement Year 2049	
Furniture Fixtures & Equipment	
Appliance Package - Kitchen	7,786
Wall Oven Double	3,793
Total for 2049	\$11,580

Description	Expenditures
Replacement Year 2050	
Streets & Parking Lots	
Bradley Creek Parkway - 2 Lift	409,943
Connector Street	22,450
Hidden Meadow Court	244,714
Holly Green Court	56,004
Paddle Creek Drive	161,859
Ridgeview Drive	156,909
Sandy Point Court	25,303
Spring Valley Court	131,880
Woodbridge Crossing Court	40,190
Swimming Pool	
Pool Resurfacing/Tile	325,461
Total for 2050	\$1,574,714



Community Advisors Page 4-9 March 26, 2021

Rolling Hills CDD Green Cove Springs, Florida Asset Current Cost by Category



			and the		*	<u>^</u>		
.	On Solution	20 20 20 20 20 20 20 20 20 20 20 20 20 2	40 50 50 40 70		A Willie	Jines Jins	JAN COST	C ^{MC} COS
Description	$\mathcal{O}_{\mathbf{a}} \mathcal{O}_{\mathbf{b}}$	\$0,76	ో నొ	A.	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	5	N C	C* C
Misc. Site Components								
Concrete Pavers - Entry	2009	2033	25	0	12	1,560 Square Feet	8.00	12,480
Concrete Pavers - Resident's Club	2009	2038	30	0	17	1,029 Square Feet	8.00	8,232
Mail Box Pedestals	2020	2044	25	0	23	4 Each	1,600.00	6,400
Street Signs/Poles	2009	2038	30	0	17	17 Each	1,200.00	20,400
Wood Boardwalk Frame/Rails/Deck (not pil	i2009	2033	25	0	12	2,280 Square Feet	28.00	63,840
Misc. Site Components - Total								\$111,352
Streets & Parking Lots								
Asphalt Mill/Overlay 1 1/2" - Parking Lot	2009	2030	22	0	9	5,623 Square Yards	16.80	94,466
Bradley Creek Parkway - 2 Lift	2009	2030	20	2	9	11,924 Square Yards	16.80	200,323
Bradley Creek Pkwy - 1 Lift	2022	2041	20	20	20	2,648 Square Yards	16.80	44,486
Connector Street	2009	2030	20	2	9	653 Square Yards	16.80	10,970
Hidden Meadow Court	2009	2030	20	2	9	7,118 Square Yards	16.80	119,582
Holly Green Court	2009	2030	20	2	9	1,629 Square Yards	16.80	27,367
Laurel Springs Drive - 1 Lift	2022	2041	20	20	20	3,009 Square Yards	16.80	50,551
Paddle Creek Drive	2009	2030	20	2	9	4,708 Square Yards	16.80	79,094
Ridgeview Drive	2009	2030	20	2	9	4,564 Square Yards	16.80	76,675
Sandy Point Court	2009	2030	20	2	9	736 Square Yards	16.80	12,365
Spring Valley Court	2009	2030	20	2	9	3,836 Square Yards	16.80	64,445
Woodbridge Crossing Court	2009	2030	20	2	9	1,169 Square Yards	16.80	19,639
Streets & Parking Lots - Total								\$799,966
Site Lighting								
Decorative Light Poles - Amenity	2009	2032	24	0	11	16 Each	2,100.00	33,600
Light Poles Shoebox Fixtures - Tennis Court	ts 2009	2032	24	0	11	36 Each	1,800.00	64,800
Site Lighting - Total								\$98,400
Fencing								
Aluminum Fence - Pool	2009	2038	30	0	17	790 Lineal Feet	32.00	25,280
Chain Link Fence VC 10 Ft - Tennis Courts		2030	24	0	11	1,386 Lineal Feet	33.60	46,570
Fencing - Total	2007	2032	21	0	11	1,500 Emiliar root	33.00	\$71,850
Misc. Building Components								
Aluminum Gutters/DS - Resident's Club & .		2038	30	0	17	362 Lineal Feet	8.20	2,968
Refurbishment Allowance - Family Restroor		2028	20	0	7	2 Each	2,200.00	4,400
Refurbishment Allowance - Fitness Locker .		2028	20	0	7	300 Square Feet	65.00	19,500
Refurbishment Allowance - Pavilion Restroo		2028	20	0	7	256 Square Feet	65.00	16,640
Refurbishment Allowance - Pool Restrooms		2028	20	0	7 17	530 Square Feet	65.00	34,450
Vinyl Railings - Porch Wood Deck - Porch	2009 2009	2038 2028	30 20	0 0	17 7	49 Lineal Feet	55.00 6.90	2,695 1,711
Misc. Building Components - Total	2009	2028	20	U	/	248 Square Feet	0.90	<u>1,711</u> \$82,365
whise. Building Components - Total								φ02,303

Community Advisors Page 5-1 March 26, 2021

		,	and the second		, The	. \$		
Description	Contraction of the second seco		st Vali	<u>ک</u>	Strue Mil	jir Jins	Jan Cost	Charles Contraction
Description	ర్త స్త్ర	\$° 4	5	∇	æ	\$ ⁴	\$* C*	C
Roofing								
Asphalt Shingles - Pavilion	2009	2038	30	0	17	41 Squares	480.00	19,680
Asphalt Shingles - Resident's Club	2009	2038	30	0	17	96 Squares	480.00	46,080
Metal Roof - Picnic Pavilion	2009	2038	30	0	17	452 Square Feet	7.80	3,526
Metal Roof - Pool Monitor	2009	2038	30	0	17	190 Square Feet	7.80	1,482
Metal Roof - Resident's Club	2009	2038	30	0	17	714 Square Feet	7.80	5,569
Metal Roof - Tennis Pavilion Roofing - Total	2009	2038	30	0	17	520 Square Feet	7.80	$\frac{4,056}{\$80,393}$
Exterior Painting								
Picnic Pavilion	2009	2021	10	0	0	1 Lump Sum	1,600.00	1,600
Pool Pavilion	2009	2021	10	0	0	3,420 Square Feet	1.60	5,472
Resident's Club	2009	2021	10	0	0	6,200 Square Feet	1.65	10,230
Tennis Pavilion	2009	2021	10	0	0	1 Lump Sum	1,600.00	1,600
Exterior Painting - Total								\$18,902
Flooring								
Carpet - Resident's Club Great Room	2009	2021	12	0	0	46 Square Yards	36.00	1,656
Carpet - Resident's Club Offices	2009	2021	12	0	0	48 Square Yards	36.00	1,728
Floor Tile - 1st Floor	2009	2038	30	0	17	432 Square Feet	12.00	5,184
Floor Tile - Lobby	2009	2038	30	0	17	340 Square Feet	12.00	4,080
Rubber Flooring - Fitness Room	2009	2033	25	0	12	56 Square Yards	40.00	2,240
Vinyl Flooring - Kids Zone	2009	2033	25	0	12	780 Square Feet	5.30	4,134
Flooring - Total								\$19,022
Cabinets & Tops								
Top/Sink - Pavilion	2009	2033	25	0	12	1 Each	1,000.00	1,000
Wood Cabinets & SS Tops - Kitchen	2009	2028	20	0	7	18 Lineal Feet	165.00	2,970
Wood Cabinets & SS Tops - Reception/Conf		2028	20	Ő	7	31 Lineal Feet	165.00	5,115
Cabinets & Tops - Total								\$9,085
Furniture Firstures & Farinment								
Furniture Fixtures & Equipment	2000	2025	10	F	4	1 J	2 000 00	2 000
Appliance Package - Kitchen Fitness Equip. Full Replace Allowance	2009 2009	2025 2036	12	5 3	4 15	1 Lump Sum 1 Lump Sum	3,900.00	3,900
Furniture Allowance - Resident's Club	2009	2030	25 20	0	13 7	1 Lump Sum 1 Lump Sum	25,000.00 5,000.00	25,000 5,000
Pool/Deck Furniture Full Replacement Allo.		2028	20 22	0	9	1 Lump Sum 1 Lump Sum	30,000.00	30,000
Wall Oven Double	2009	2030	12	5	4	1 Each	1,900.00	1,900
Furniture Fixtures & Equipment - Total	2007	2025	12	5	-	1 Lach	1,700.00	\$65,800
HVAC Equipment	• • • •			_	-			
Heat Pump 1 - 10 Ton	2009	2023	12	3	2	1 Each	16,000.00	16,000
Heat Pump 2 - 8 Ton	2009	2023	12	3	2	1 Each	12,800.00	12,800
Heat Pump 3 - 7 Ton	2009	2023	12	3	2	1 Each	11,200.00	<u>11,200</u>
HVAC Equipment - Total								\$40,000

Community Advisors Page 5-2 March 26, 2021





JANCOS

Description

Swimming Pool								
Concrete Pavers - Pool	2009	2038	30	0	17	19,327 Square Feet	8.00	154,616
Fiberglass Refurbishment Allow - Pool Slid		2023	12	3	2	1 Lump Sum	15,000.00	15,000
Lane Divider Reel	2009	2038	30	0	17	1 Each	2,700.00	2,700
Lane Dividers	2009	2023	12	3	2	6 Lanes	530.00	3,180
Play Equip. Refurbishment Allow - Splash		2023	12	3	2	1 Lump Sum	5,000.00	5,000
Pool Filtration Refurbishment Allowance	2007	2036	30	0	15	1 Lump Sum	40,000.00	40,000
Pool Lift	2009	2028	20	0	7	2 Each	3,200.00	6,400
Pool Resurfacing/Tile	2009	2026	12	6	5	11,200 Square Feet	14.20	159,040
Shade Structure Fabric - Pool	2009	2023	12	3	2	5 Each	2,400.00	12,000
Shade Structure Frame - Pool	2009	2033	25	0	12	5 Each	6,800.00	34,000
Starting Blocks	2009	2028	20	0	7	6 Each	2,100.00	12,600
Steel Stair Refurbishment Allowance	2009	2033	25	0	12	1 Lump Sum	15,000.00	15,000
Swimming Pool - Total								\$459,536
Tennis Courts								
Asphalt Resufacing (color coat)	2016	2023	7	1	2	4,684 Square Yards	8.20	38,409
Shade Structure Frame - Tennis Courts	2009	2033	25	0	12	3 Each	3,200.00	9,600
Tennis Courts - Total								\$48,009
Playground								
Park Bench Expanded Metal	2009	2028	20	0	7	2 Each	1,200.00	2,400
Plastic Play Surface Border	2009	2028	20	0	, 7	246 Lineal Feet	14.00	3,444
Play Equipment Allowance	2009	2028	15	5	7	1 Lump Sum	30,000.00	30,000
Swings Two Bay Arched	2009	2028	15	5	7	1 Each	4,200.00	4,200
Playground - Total				-			.,	\$40,044
Components Not Included								
Asphalt Seal Coat	Ui	nfunded						
Building Sign	Ui	nfunded						
Ceiling Fans	Ui	nfunded						
Community Signs	Ui	nfunded						
Concrete Curbs/Walks	Ui	nfunded						
Doors/Windows	Ui	nfunded						
Dumpster Enclosure/Gates	U_{i}	nfunded						
Electric Lift	Ui	nfunded						

Unfunded Fitness Equipment Partial Replace Allowance Unfunded Flag Pole Unfunded Gas Grill Unfunded Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Nets/Poles - Tennis Courts Unfunded Pond Fountains/Aerators Unfunded

> Community Advisors Page 5-3 March 26, 2021

A Contraction of the second se A Signa Portiningo . 150 Jul One coline Jit

ري منتقري

Cateor Cost

Description

Components Not Included continued... Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Rubber Play Surface - Playground Shade Structure Fabric - Tennis Courts Stormwater Pond Dredging/Pipe/Structures Tennis Court Replacement Utility Lines Volley Ball Court Water Cooler - Tennis Courts Water Coolers Components Not Included - Total

Unfunded Unfunded

Total Asset Summary

\$1,944,722

Community Advisors Page 5-4 March 26, 2021

Asset II	DDescription	Replacement	Page
Misc. S	ite Components		
1073	Concrete Pavers - Entry	2033	5-9
1003	Concrete Pavers - Resident's Club	2038	5-9
1077	Mail Box Pedestals	2044	5-10
1075	Street Signs/Poles	2038	5-10
1094	Wood Boardwalk Frame/Rails/Deck (not pilings)	2033	5-11
Streets	& Parking Lots		
1067	Asphalt Mill/Overlay 1 1/2" - Parking Lot	2030	5-12
1080	Bradley Creek Parkway - 2 Lift	2030	5-12
1089	Bradley Creek Pkwy - 1 Lift	2041	5-13
1090	Connector Street	2030	5-13
1082	Hidden Meadow Court	2030	5-13
1088	Holly Green Court	2030	5-14
1081	Laurel Springs Drive - 1 Lift	2041	5-14
1084	Paddle Creek Drive	2030	5-14
1087	Ridgeview Drive	2030	5-15
1085	Sandy Point Court	2030	5-15
1086	Spring Valley Court	2030	5-15
1093	Woodbridge Crossing Court	2030	5-16
Site Lig	ghting		
1031	Decorative Light Poles - Amenity	2032	5-17
1059	Light Poles Shoebox Fixtures - Tennis Courts	2032	5-17
Fencing	3		
1029	Aluminum Fence - Pool	2038	5-18
1057	Chain Link Fence VC 10 Ft - Tennis Courts	2032	5-18
Misc. B	Building Components		
1018	Aluminum Gutters/DS - Resident's Club & Pavilion	2038	5-19
1013	Refurbishment Allowance - Family Restroom	2028	5-19
1012	Refurbishment Allowance - Fitness Locker Rooms	2028	5-20
1054	Refurbishment Allowance - Pavilion Restrooms	2028	5-20
1028	Refurbishment Allowance - Pool Restrooms	2028	5-21
1019	Vinyl Railings - Porch	2038	5-21
1020	Wood Deck - Porch	2028	5-22

Asset I	DDescription	Replacement	Page
Roofin	0		
1051	Asphalt Shingles - Pavilion	2038	5-23
1001	Asphalt Shingles - Resident's Club	2038	5-23
1095	Metal Roof - Picnic Pavilion	2038	5-24
1026	Metal Roof - Pool Monitor	2038	5-24
1091	Metal Roof - Resident's Club	2038	5-25
1063	Metal Roof - Tennis Pavilion	2038	5-25
Exterio	or Painting		
1096	Picnic Pavilion	2021	5-26
1050	Pool Pavilion	2021	5-26
1000	Resident's Club	2021	5-20 5-27
1052	Tennis Pavilion	2021	5-27
1005		2021	5 21
Floorin	g		
1014	Carpet - Resident's Club Great Room	2021	5-28
1006	Carpet - Resident's Club Offices	2021	5-28
1102	Floor Tile - 1st Floor	2038	5-29
1009	Floor Tile - Lobby	2038	5-29
1010	Rubber Flooring - Fitness Room	2033	5-30
1103	Vinyl Flooring - Kids Zone	2033	5-30
Cabine	ts & Tops		
1053	Top/Sink - Pavilion	2033	5-31
1015	Wood Cabinets & SS Tops - Kitchen	2028	5-31
1007	Wood Cabinets & SS Tops - Reception/Conf. Rm	2028	5-32
Furniti	ıre Fixtures & Equipment		
1017	Appliance Package - Kitchen	2025	5-33
1106	Fitness Equip. Full Replace Allowance	2036	5-33
1016	Furniture Allowance - Resident's Club	2028	5-34
1039	Pool/Deck Furniture Full Replacement Allowance	2030	5-35
1025	Wall Oven Double	2025	5-35
HVAC	Equipment		
1105	Heat Pump 1 - 10 Ton	2023	5-36
1104	Heat Pump 2 - 8 Ton	2023	5-36
1023	Heat Pump 3 - 7 Ton	2023	5-36
	-		

Asset I	DDescription	Replacement	Page
Swimn	ning Pool		
1030	Concrete Pavers - Pool	2038	5-37
1036	Fiberglass Refurbishment Allow - Pool Slide	2023	5-37
1055	Lane Divider Reel	2038	5-38
1056	Lane Dividers	2023	5-38
1043	Play Equip. Refurbishment Allow - Splash Pool	2023	5-39
1107	Pool Filtration Refurbishment Allowance	2036	5-39
1042	Pool Lift	2028	5-39
1032	Pool Resurfacing/Tile	2026	5-40
1035	Shade Structure Fabric - Pool	2023	5-41
1033	Shade Structure Frame - Pool	2033	5-41
1037	Starting Blocks	2028	5-42
1040	Steel Stair Refurbishment Allowance	2033	5-42
Tennis	Courts		
1058	Asphalt Resufacing (color coat)	2023	5-43
1060	Shade Structure Frame - Tennis Courts	2033	5-43
Playgro	ound		
1049	Park Bench Expanded Metal	2028	5-45
1046	Plastic Play Surface Border	2028	5-45
1044	Play Equipment Allowance	2028	5-46
1048	Swings Two Bay Arched	2028	5-46
-	onents Not Included		
1068	Asphalt Seal Coat	Unfunded	5-47
1005	Building Sign	Unfunded	5-47
1021	Ceiling Fans	Unfunded	5-48
1078	Community Signs	Unfunded	5-48
1071	Concrete Curbs/Walks	Unfunded	5-49
1022	Doors/Windows	Unfunded	5-49
1069	Dumpster Enclosure/Gates	Unfunded	5-49
1008	Electric Lift	Unfunded	5-50
1011	Fitness Equipment Partial Replace Allowance	Unfunded	5-50
1002	Flag Pole	Unfunded	5-51
1052	Gas Grill	Unfunded	5-51
1099	Irrigation System	Unfunded	5-52
1100	Landscaping	Unfunded	5-52

Asset II	DDescription	Replacement	Page
Compo	nents Not Included Continued		
1070	Light Poles - Parking Lot	Unfunded	5-52
1074	Monument Sign Refurbishment	Unfunded	5-53
1064	Nets/Poles - Tennis Courts	Unfunded	5-53
1101	Pond Fountains/Aerators	Unfunded	5-54
1108	Pool Filtration Partial Replacement	Unfunded	5-54
1038	Pool/Deck Furniture Partial Replacement	Unfunded	5-54
1004	Railings	Unfunded	5-55
1047	Rubber Play Surface - Playground	Unfunded	5-55
1061	Shade Structure Fabric - Tennis Courts	Unfunded	5-56
1076	Stormwater Pond Dredging/Pipe/Structures	Unfunded	5-56
1045	Tennis Court Replacement	Unfunded	5-57
1098	Utility Lines	Unfunded	5-57
1050	Volley Ball Court	Unfunded	5-58
1062	Water Cooler - Tennis Courts	Unfunded	5-58
1027	Water Coolers	Unfunded	5-59
	Total Funded Assets	73	
	Total Unfunded Assets	28	
	Total Assets	101	

Concrete Pavers	- Entry - 2033
------------------------	----------------

Asset ID 1073

	Misc. Site Components
Placed in Service	January 2009
Useful Life	25
Replacement Year	2033
Remaining Life	12

1,560 Square Feet	@ \$8.00
Asset Actual Cost	\$12,480.00
Percent Replacement	100%
Future Cost	\$16,784.21



Concrete Pavers - Resident's Club - 2038

Asset ID

1003

30

17

2038

Misc. Site Components Placed in Service January 2009 Useful Life Replacement Year Remaining Life

1,029 Square Feet	@ \$8.00
Asset Actual Cost	\$8,232.00
Percent Replacement	100%
Future Cost	\$12,525.96



Community Advisors Page 5-9 March 26, 2021

1077

Mail Box Pedestals - 2044

Asset ID

	Misc. Site Components
Placed in Service	January 2020
Useful Life	25
Replacement Year	2044
Remaining Life	23

 4 Each
 @ \$1,600.00

 Asset Actual Cost
 \$6,400.00

 Percent Replacement
 100%

 Future Cost
 \$11,293.51



Street Signs/Poles - 2038		17 Each	@ \$1,200.00
Asset ID	1075	Asset Actual Cost	\$20,400.00
		Percent Replacement	100%
Misc.	Site Components	Future Cost	\$31,041.01
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Community Advisors Page 5-10 March 26, 2021

Wood Boardwalk Frame	e/Rails/Deck (not pili	ngs) - 2033	
Asset ID	1094	2,280 Square Feet Asset Actual Cost Percent Replacement	@ \$28.00 \$63,840.00 100%
Misc	. Site Components	Future Cost	\$85,857.70
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	2033		
Remaining Life	12		



Community Advisors Page 5-11 March 26, 2021

Asphalt Mill/Overlay 1	1/2" - Parking Lot - 2	.030	
Asset ID	1067	5,623 Square Yards Asset Actual Cost Percent Replacement	@ \$16.80 \$94,466.40 100%
Stree	ets & Parking Lots	Future Cost	\$117,975.59
Placed in Service	January 2009		
Useful Life	22		
Replacement Year	2030		
Remaining Life	9		



Bradley Creek Parkway - 2 Lift - 2030

Asset ID	1080

	Streets & Parking Lots
Placed in Service	January 2009
Useful Life	20
Adjustment	2
Replacement Year	2030
Remaining Life	9

@ \$16.80
\$200,323.20
100%
\$250,176.23

Bradley Creek Pkwy - 1	Lift - 2041		
Asset ID	1089	2,648 Square Yards Asset Actual Cost Percent Replacement	@ \$16.80 \$44,486.40 100%
Stree	ets & Parking Lots	Future Cost	\$72,896.15
Placed in Service	January 2022		¢, 2, 0,0,10
Useful Life	20 20		
Adjustment	20 20		
Replacement Year	2041		
Remaining Life	2041		
Connector Street - 2030		653 Square Yards	@ \$16.80
Asset ID	1090	Asset Actual Cost	\$10,970.40
		Percent Replacement	100%
Stree	ets & Parking Lots	Future Cost	\$13,700.53
Placed in Service	January 2009		. ,
Useful Life	20		
Adjustment	2		
Replacement Year	2030		
Remaining Life	9		
Hidden Meadow Court -	2030	7,118 Square Yards	@ \$16.80
Asset ID	1082	Asset Actual Cost	\$119,582.40
		Percent Replacement	100%
Stree	ets & Parking Lots	Future Cost	\$149,342.03
Placed in Service	January 2009		,-
Useful Life	20		
Adjustment	2		
Replacement Year	2030		
Remaining Life	9		
\mathcal{O}	-		

Component Detail Holly Green Court - 2030 1,629 Square Yards @ \$16.80 Asset ID 1088 Asset Actual Cost \$27,367.20 Percent Replacement 100% Streets & Parking Lots Future Cost \$34,177.88 Placed in Service January 2009 Useful Life 20 Adjustment 2 2030 Replacement Year **Remaining Life** 9 Laurel Springs Drive - 1 Lift - 2041 3,009 Square Yards @ \$16.80 Asset ID 1081 Asset Actual Cost \$50,551.20 Percent Replacement 100% Future Cost Streets & Parking Lots \$82,834.03 Placed in Service January 2022 Useful Life 20 Adjustment 20 **Replacement Year** 2041 **Remaining Life** 20 Paddle Creek Drive - 2030 4,708 Square Yards @ \$16.80 Asset Actual Cost Asset ID 1084 \$79,094.40 Percent Replacement 100% Future Cost Streets & Parking Lots \$98,778.07 Placed in Service January 2009 Useful Life 20 Adjustment 2 **Replacement Year** 2030 **Remaining Life** 9

Rolling Hills CDD

	Component L	Detail	
Ridgeview Drive - 2030		4,564 Square Yards	@ \$16.80
Asset ID	1087	Asset Actual Cost	\$76,675.20
		Percent Replacement	100%
Street	s & Parking Lots	Future Cost	\$95,756.82
Placed in Service	January 2009		
Useful Life	20		
Adjustment	2		
Replacement Year	2030		
Remaining Life	9		
Sandy Point Court - 2030		736 Square Yards	@ \$16.80
Asset ID	1085	Asset Actual Cost	\$12,364.80
Asset ID	1005	Percent Replacement	100%
Street	s & Parking Lots	Future Cost	\$15,441.94
Placed in Service	January 2009	i utule cost	$\psi_{1,2}, ++1, 2$
Useful Life	20 Sundary 2009		
Adjustment	20		
Replacement Year	2030		
Remaining Life	9		
Spring Valley Court - 203	30	3,836 Square Yards	@ \$16.80
Asset ID	1086	Asset Actual Cost	\$64,444.80
		Percent Replacement	100%
Street	s & Parking Lots	Future Cost	\$80,482.72
Placed in Service	January 2009		
Useful Life	20		
Adjustment	2		
Replacement Year	2030		
Remaining Life	9		
C			

Woodbridge Crossing Court - 2030

Asset ID 1093

	Streets & Parking Lots
Placed in Service	January 2009
Useful Life	20
Adjustment	2
Replacement Year	2030
Remaining Life	9

1,169 Square Yards	@ \$16.80
Asset Actual Cost	\$19,639.20
Percent Replacement	100%
Future Cost	\$24,526.67

Community Advisors Page 5-16 March 26, 2021

Decorative Light Poles	- Amenity - 2032	16 Each	@ \$2,100.00
Asset ID	1031	Asset Actual Cost Percent Replacement	\$33,600.00 100%
	Site Lighting	Future Cost	\$44,086.11
Placed in Service	January 2009		
Useful Life	24		
Replacement Year	2032		
Remaining Life	11		



Light Poles Shoebox Fixtures - Tennis Courts - 2032

Asset ID	1059	36 Each Asset Actual Cost Percent Replacement	@ \$1,800.00 \$64,800.00 100%
	Site Lighting	Future Cost	\$85,023.22
Placed in Service	January 2009		
Useful Life	24		
Replacement Year	2032		
Remaining Life	11		



Community Advisors Page 5-17 March 26, 2021

Aluminum Fence - Pool	- 2038	790 Lineal Feet	@ \$32.00
Asset ID	1029	Asset Actual Cost	\$25,280.00
		Percent Replacement	100%
	Fencing	Future Cost	\$38,466.51
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Chain Link Fence VC 10 Ft - Tennis Courts - 2032

		1,386 Lineal Feet	@ \$33.60
Asset ID	1057	Asset Actual Cost	\$46,569.60
		Percent Replacement	100%
	Fencing	Future Cost	\$61,103.35
Placed in Service	January 2009		
Useful Life	24		
Replacement Year	2032		
Remaining Life	11		



Community Advisors Page 5-18 March 26, 2021

Aluminum Gutters/DS -	- Resident's Club & Pa	avilion - 2038	
		362 Lineal Feet	@ \$8.20
Asset ID	1018	Asset Actual Cost	\$2,968.40
		Percent Replacement	100%
Misc. Bu	uilding Components	Future Cost	\$4,516.77
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Refurbishment Allowance - Family Restroom - 2028

Asset ID	1013
Misc. B	Building Components
Placed in Service	January 2009
Useful Life	20
Replacement Year	2028
Remaining Life	7

@ \$2,200.00
\$4,400.00
100%
\$5,230.22



Community Advisors Page 5-19 March 26, 2021

ance - Fitness Lock	er Rooms - 2028
1012	300 Sc
1012	Asset Ac
	Percent Re
Building Components	Fu
January 2009	
20	
2028	
7	
	1012 Building Components January 2009 20

300 Square Feet@ \$65.00Asset Actual Cost\$19,500.00Percent Replacement100%Future Cost\$23,179.37



Refurbishment Allowance - Pavilion Restrooms - 2028

Asset ID	1054
Misc. Buil Placed in Service	ding Components January 2009
Useful Life	20
Replacement Year Remaining Life	2028 7
υ	

@ \$65.00
\$16,640.00
100%
\$19,779.73



Community Advisors Page 5-20 March 26, 2021

Refurbishment Allowance - Pool Restrooms - 2028				
		530 Square Feet	@ \$65.00	
Asset ID	1028	Asset Actual Cost	\$34,450.00	
		Percent Replacement	100%	
Misc. Buil	ding Components	Future Cost	\$40,950.22	
Placed in Service	January 2009			
Useful Life	20			
Replacement Year	2028			
Remaining Life	7			



1019

Vinyl Railings - Porch - 2038

Asset ID

Misc. Building Components Placed in Service January 2009 Useful Life 30 Replacement Year 2038 Remaining Life 17

49 Lineal Feet	@ \$55.00
Asset Actual Cost	\$2,695.00
Percent Replacement	100%
Future Cost	\$4,100.76



Community Advisors Page 5-21 March 26, 2021

Wood	Deck -	Porch -	2028	
wood	Deck -	Porcn -	2028	

Asset ID 1020

Misc. Building Components Placed in Service January 2009 Useful Life 20 Replacement Year 2028 Remaining Life 7

248 Square Feet	@ \$6.90
Asset Actual Cost	\$1,711.20
Percent Replacement	100%
Future Cost	\$2,034.08



Asphalt Shingles - Pavil	ion - 2038	41 Squares	@ \$480.00
Asset ID	1051	Asset Actual Cost	\$19,680.00
		Percent Replacement	100%
	Roofing	Future Cost	\$29,945.45
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Asphalt Shingles - Resident's Club - 2038

Asset ID	1001
	Roofing
Placed in Service	January 2009
Useful Life	30
Replacement Year	2038
Remaining Life	17

96 Squares	@ \$480.00
Asset Actual Cost	\$46,080.00
Percent Replacement	100%
Future Cost	\$70,116.17



Community Advisors Page 5-23 March 26, 2021

Asset ID

Placed in Service Useful Life Replacement Year Remaining Life

1095
Roofing
January 2009
30
2038
17

@ \$7.80
\$3,525.60
100%
\$5,364.62



Metal Roof - Pool Moni	tor - 2038	190 Square Feet	@ \$7.80
Asset ID	1026	Asset Actual Cost	\$1,482.00
		Percent Replacement	100%
	Roofing	Future Cost	\$2,255.04
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Community Advisors Page 5-24 March 26, 2021

Metal Roof - Resident's	Club - 2038		
Asset ID	1091	714 Square Feet Asset Actual Cost Percent Replacement	@ \$7.80 \$5,569.20 100%
	Roofing	Future Cost	\$8,474.20
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Metal Roof - Tennis Pavilion - 2038

Asset ID	1063	520 Square Feet Asset Actual Cost Percent Replacement	@ \$7.80 \$4,056.00 100%
	Roofing	Future Cost	\$6,171.68
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Community Advisors Page 5-25 March 26, 2021

Picnic Pavilion - 2021		1 Lump Sum	@ \$1,600.00
Asset ID	1096	Asset Actual Cost	\$1,600.00
		Percent Replacement	100%
	Exterior Painting	Future Cost	\$1,600.00
Placed in Service	January 2009		
Useful Life	10		
Replacement Year	2021		
Remaining Life	0		



Pool Pavilion - 2021		3,420 Square Feet	@ \$1.60
Asset ID	1066	Asset Actual Cost	\$5,472.00
		Percent Replacement	100%
	Exterior Painting	Future Cost	\$5,472.00
Placed in Service	January 2009		
Useful Life	10		
Replacement Year	2021		
Remaining Life	0		



Community Advisors Page 5-26 March 26, 2021

Resident's Club - 2021		6,200 Square Feet	@ \$1.65
Asset ID	1092	Asset Actual Cost	\$10,230.00
		Percent Replacement	100%
	Exterior Painting	Future Cost	\$10,230.00
Placed in Service	January 2009		
Useful Life	10		
Replacement Year	2021		
Remaining Life	0		
	X HE	All and a second se	



Tennis Pavilion - 2021		1 Lump Sum	@ \$1,600.00
Asset ID	1065	Asset Actual Cost	\$1,600.00
		Percent Replacement	100%
	Exterior Painting	Future Cost	\$1,600.00
Placed in Service	January 2009		
Useful Life	10		
Replacement Year	2021		
Remaining Life	0		



Community Advisors Page 5-27 March 26, 2021

Carpet - Resident's Club	Great Room - 2021		
Asset ID	1014	46 Square Yards Asset Actual Cost Percent Replacement	@ \$36.00 \$1,656.00 100%
	Flooring	Future Cost	\$1,656.00
Placed in Service	January 2009		
Useful Life	12		
Replacement Year	2021		
Remaining Life	0		



Carpet - Resident's Club Offices - 2021

Asset ID	1006
	Flooring
Placed in Service	January 2009
Useful Life	12
Replacement Year	2021
Remaining Life	0

48 Square Yards	@ \$36.00
Asset Actual Cost	\$1,728.00
Percent Replacement	100%
Future Cost	\$1,728.00



Community Advisors Page 5-28 March 26, 2021

Floor Tile - 1st Floor - 2	2038	432 Square Feet	@ \$12.00
Asset ID	1102	Asset Actual Cost	\$5,184.00
		Percent Replacement	100%
	Flooring	Future Cost	\$7,888.07
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		



Floor Tile - Lobby - 2038	
A cost ID	

Asset ID

1009

Placed in Service Useful Life Replacement Year Remaining Life

F looring
Flooring
January 2009
30
2038
17

340 Square Feet Asset Actual Cost Percent Replacement Future Cost

@ \$12.00
\$4,080.00
100%
\$6,208.20



Community Advisors Page 5-29 March 26, 2021

Rubber Flooring - Fitnes	ss Room - 2033		
Asset ID	1010	56 Square Yards Asset Actual Cost Percent Replacement	@ \$40.00 \$2,240.00 100%
	Flooring	Future Cost	\$3,012.55
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	2033		
Remaining Life	12		



Vinyl Flooring - Kids Zo	one - 2033	780 Square Feet	@ \$5.30
Asset ID	1103	Asset Actual Cost	\$4,134.00
		Percent Replacement	100%
	Flooring	Future Cost	\$5,559.77
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	2033		
Remaining Life	12		



Community Advisors Page 5-30 March 26, 2021

Top/Sink - Pavilion - 20)33	1 Each	@ \$1,000.00
Asset ID	1053	Asset Actual Cost	\$1,000.00
		Percent Replacement	100%
	Cabinets & Tops	Future Cost	\$1,344.89
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	2033		
Remaining Life	12		



Wood Cabinets & SS Tops - Kitchen - 2028

Asset ID

Placed in Service Useful Life Replacement Year Remaining Life

Cabinets & Tops
January 2009
20
2028
7

1015

18 Lineal Feet@ \$165.00Asset Actual Cost\$2,970.00Percent Replacement100%Future Cost\$3,530.40



Community Advisors Page 5-31 March 26, 2021

Wood Cabinets & SS Tops - Reception/Conf. Rm - 2	028
--	-----

Asset ID	1007	31 Lineal Feet Asset Actual Cost	@ \$165.00 \$5,115.00
		Percent Replacement	100%
	Cabinets & Tops	Future Cost	\$6,080.13
Placed in Service	January 2009		
Useful Life	20		
Replacement Year	2028		
Remaining Life	7		



Community Advisors Page 5-32 March 26, 2021

Appliance Package - Kitchen - 2025

Asset ID 1017

Furniture Fixtures & Equipment		
Placed in Service	January 2009	
Useful Life	12	
Adjustment	5	
Replacement Year	2025	
Remaining Life	4	

1 Lump Sum	@ \$3,900.00
Asset Actual Cost	\$3,900.00
Percent Replacement	100%
Future Cost	\$4,304.87



Fitness Equip. Full Replace Allowance - 2036

Asset ID	1106
Furniture Fixtures	& Equipment
Placed in Service	January 2009
Useful Life	25
Adjustment	3
Replacement Year	2036
Remaining Life	15

1 Lump Sum	@ \$25,000.00
Asset Actual Cost	\$25,000.00
Percent Replacement	100%
Future Cost	\$36,207.45

Fitness Equip. Full Replace Allowance continued...



Furniture Allowance - Resident's Club - 2028

Asset ID	1016	1 Lump Sum Asset Actual Cost	@ \$5,000.00 \$5,000.00
		Percent Replacement	100%
Furniture Fix	tures & Equipment	Future Cost	\$5,943.43
Placed in Service	January 2009		
Useful Life	20		
Replacement Year	2028		
Remaining Life	7		



Pool/Deck Furniture Full Replacement Allowance - 2030

Asset ID	1039
Furniture Fixtures	& Equipment
Placed in Service	January 2009
Useful Life	22
Replacement Year	2030
Remaining Life	9

1 Lump Sum	@ \$30,000.00
Asset Actual Cost	\$30,000.00
Percent Replacement	100%
Future Cost	\$37,465.89



1025

Wall Oven Double - 2025

Asset ID

Furniture Fixtures & Equipment			
Placed in Service	January 2009		
Useful Life	12		
Adjustment	5		
Replacement Year	2025		
Remaining Life	4		

1 Each	@ \$1,900.00
Asset Actual Cost	\$1,900.00
Percent Replacement	100%
Future Cost	\$2,097.24



Community Advisors Page 5-35 March 26, 2021

Heat Pump 1 - 10 Tor	n - 2023	1 Each	@ \$16,000.00
Asset ID	1105	Asset Actual Cost	\$16,000.00
		Percent Replacement	100%
	HVAC Equipment	Future Cost	\$16,810.00
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	2023		
Remaining Life	2		
Heat Pump 2 - 8 Ton	- 2023	1 Each	@ \$12,800.00
Asset ID	1104	Asset Actual Cost	\$12,800.00
		Percent Replacement	100%
	HVAC Equipment	Future Cost	\$13,448.00
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	2023		
Remaining Life	2		
Heat Pump 3 - 7 Ton	- 2023	1 Each	@ \$11,200.00
Asset ID	1023	Asset Actual Cost	\$11,200.00
		Percent Replacement	100%
	HVAC Equipment	Future Cost	\$11,767.00
Placed in Service	January 2009		. ,
Useful Life	12		
Adjustment	3		
Replacement Year	2023		
Remaining Life	2		

1 - 2038	19,327 Square Feet	@ \$8.00
1030	Asset Actual Cost	\$154,616.00
	Percent Replacement	100%
Swimming Pool	Future Cost	\$235,266.53
January 2009		
30		
2038		
17		
	1030 Swimming Pool January 2009 30 2038	1030Asset Actual Cost1030Asset Actual CostPercent ReplacementFuture CostJanuary 20093020382038



Fiberglass Refurbishment Allow - Pool Slide - 2023

		1 Lump Sum	@ \$15,000.00
Asset ID	1036	Asset Actual Cost	\$15,000.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$15,759.37
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	2023		
Remaining Life	2		



Community Advisors Page 5-37 March 26, 2021

Lane Divider Reel - 2038	J	1 Each	@ \$2,700.00
Asset ID	1055	Asset Actual Cost	\$2,700.00
		Percent Replacement	100%
S	Swimming Pool	Future Cost	\$4,108.37
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	2038		
Remaining Life	17		

Lane Dividers - 2023		6 Lanes	@ \$530.00
Asset ID	1056	Asset Actual Cost	\$3,180.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$3,340.99
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	2023		
Remaining Life	2		



Community Advisors Page 5-38 March 26, 2021

Play Equip. Refurbishn	nent Allow - Splash P	ool - 2023	
		1 Lump Sum	@ \$5,000.00
Asset ID	1043	Asset Actual Cost	\$5,000.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$5,253.12
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	2023		
Remaining Life	2		



Pool Filtration Refurbishment Allowance - 2036

		1 Lump Sum	@ \$40,000.00
Asset ID	1107	Asset Actual Cost	\$40,000.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$57,931.93
Placed in Service	January 2007		
Useful Life	30		
Replacement Year	2036		
Remaining Life	15		
Pool Lift - 2028 Asset ID Placed in Service Useful Life	1042 Swimming Pool January 2009 20	2 Each Asset Actual Cost Percent Replacement Future Cost	@ \$3,200.00 \$6,400.00 100% \$7,607.59
Replacement Year	2028		
Remaining Life	7		

Pool Lift continued...



Pool Resurfacing/Tile - 2026	
Asset ID	

	Swimming Pool
Placed in Service	January 2009
Useful Life	12
Adjustment	6
Replacement Year	2026
Remaining Life	5

11,200 Square Feet	@ \$14.20
Asset Actual Cost	\$159,040.00
Percent Replacement	100%
Future Cost	\$179,939.16



Shade Structure Fabr	ic - Pool - 2023		5 Each	@ \$2,400.00
Asset ID	103	5	Asset Actual Cost Percent Replacement	\$12,000.00 100%
	Swimming Poo	ol	Future Cost	\$12,607.50
Placed in Service	January 200	9		
Useful Life	12	2		
Adjustment		3		
Replacement Year	202	3		
Remaining Life	,	2		



Shade Structure Frame	- Pool - 2033	5 Each	@ \$6,800.00
Asset ID	1033	Asset Actual Cost	\$34,000.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$45,726.22
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	2033		
Remaining Life	12		



Community Advisors Page 5-41 March 26, 2021

Starting Blocks - 2028		6 Each	@ \$2,100.00
Asset ID	1037	Asset Actual Cost	\$12,600.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$14,977.44
Placed in Service	January 2009		
Useful Life	20		
Replacement Year	2028		
Remaining Life	7		
	Por la		



1040

Steel Stair Refurbishment Allowance - 2033

Asset	ID
-------	----

Placed in Service Useful Life Replacement Year Remaining Life

Swimming Pool January 2009
25
2033
12

1 Lump Sum	@ \$15,000.00
Asset Actual Cost	\$15,000.00
Percent Replacement	100%
Future Cost	\$20,173.33



Community Advisors Page 5-42 March 26, 2021

Asphalt Resufacing (color coat) - 2023

Asset ID	1058
Placed in Service Useful Life Adjustment Replacement Year Remaining Life	Tennis Courts January 2016 7 1 2023 2

4,684 Square Yards	@ \$8.20
Asset Actual Cost	\$38,408.80
Percent Replacement	100%
Future Cost	\$40,353.25



Shade Structure Frame - Tennis Courts - 2033

Asset ID	1060	3 Each Asset Actual Cost Percent Replacement	@ \$3,200.00 \$9,600.00 100%
	Tennis Courts	Future Cost	\$12,910.93
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	2033		
Remaining Life	12		

Shade Structure Frame - Tennis Courts continued...



Community Advisors Page 5-44 March 26, 2021

Park Bench Expanded	l Metal - 2028	2 Each	@ \$1,200.00
Asset ID	1049	Asset Actual Cost	\$2,400.00
		Percent Replacement	100%
	Playground	Future Cost	\$2,852.85
Placed in Service	January 2009		
Useful Life	20		
Replacement Year	2028		
Remaining Life	7		



Plastic Play Surface Box	rder - 2028	246 Lineal Feet	@ \$14.00
Asset ID	1046	Asset Actual Cost	\$3,444.00
		Percent Replacement	100%
	Playground	Future Cost	\$4,093.83
Placed in Service	January 2009		
Useful Life	20		
Replacement Year	2028		
Remaining Life	7		



Community Advisors Page 5-45 March 26, 2021

Play Equipment Allowa	nce - 2028	1 Lump Sum	@ \$30,000.00
Asset ID	1044	Asset Actual Cost	\$30,000.00
		Percent Replacement	100%
	Playground	Future Cost	\$35,660.57
Placed in Service	January 2009		
Useful Life	15		
Adjustment	5		
Replacement Year	2028		
Remaining Life	7		



Swings Two Bay Arched - 202	8	1 Each	@
Asset ID	1048	Asset Actual Cost	
		Percent Replacement	
Ι	Playground	Future Cost	
Placed in Service Jan	nuary 2009		
Useful Life	15		

5

7

2028

Adjustment

Replacement Year

Remaining Life

@ \$4,200.00
\$4,200.00
100%
\$4,992.48



Community Advisors Page 5-46 March 26, 2021

Asphalt Seal Coat

Asset ID

1068

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Building Sign

Asset ID

1005

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Community Advisors Page 5-47 March 26, 2021

1021

Ceiling Fans

Asset ID

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Community Signs

Asset ID

1078

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%




Community Advisors Page 5-48 March 26, 2021

Asset ID Componen Placed in Service No Useful Life	1071 ts Not Included January 2009	Asset Actual Cost Percent Replacement Future Cost	100%
Doors/Windows Asset ID	1022	Asset Actual Cost	
	ts Not Included	Percent Replacement Future Cost	100%
Componen Placed in Service No Useful Life Dumpster Enclosure/Gates Asset ID	January 2009		100%

Dumpster Enclosure/Gates continued...





Asset ID

1008

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Fitness Equipment Parti	al Replace Allowance		
Asset ID	1011	Asset Actual Cost Percent Replacement	100%
Compor	nents Not Included	Future Cost	
Placed in Service No Useful Life	January 2009		

Community Advisors Page 5-50 March 26, 2021

Fitness Equipment Partial Replace Allowance continued...





Community Advisors Page 5-51 March 26, 2021

Gas Grill continued...



Irrigation SystemAsset ID1099Components Not IncludedPlaced in ServiceJanuary 2009No Useful Life		Asset Actual Cost Percent Replacement Future Cost	100%
Landscaping Asset ID Component Placed in Service No Useful Life	1100 s Not Included January 2009	Asset Actual Cost Percent Replacement Future Cost	100%
Light Poles - Parking Lot Asset ID Component Placed in Service No Useful Life	1070 s Not Included January 2009	Asset Actual Cost Percent Replacement Future Cost	100%

Light Poles - Parking Lot continued...



Monument Sign Refurbishment

Asset ID

1074

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Nets/Poles - Tennis Courts

Asset ID

1064

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%

Community Advisors Page 5-53 March 26, 2021

Nets/Poles - Tennis Courts continued...



Pond Fountains/Aerators Asset ID Componer Placed in Service No Useful Life	1101 nts Not Included January 2009	Asset Actual Cost Percent Replacement Future Cost	100%
Pool Filtration Partial Rep Asset ID Componen Placed in Service No Useful Life	hlacement 1108 nts Not Included January 2007	Asset Actual Cost Percent Replacement Future Cost	100%
Pool/Deck Furniture Partia Asset ID Componen Placed in Service No Useful Life	al Replacement 1038 nts Not Included January 2009	Asset Actual Cost Percent Replacement Future Cost	100%

Pool/Deck Furniture Partial Replacement continued...



Railings

Asset ID

1004

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Rubber Play Surface - Playground

Asset ID

1047

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%

Community Advisors Page 5-55 March 26, 2021

Rubber Play Surface - Playground continued...



1061

Shade Structure Fabric - Tennis Courts

Asset ID

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



1076

Stormwater Pond Dredging/Pipe/Structures

Asset ID

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%

Community Advisors Page 5-56 March 26, 2021

Stormwater Pond Dredging/Pipe/Structures continued...



Tennis Court Replacement

Asset ID

1045

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Utility Lines

Asset ID

1098

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%

Community Advisors Page 5-57 March 26, 2021

Volley Ball Court

Asset ID

1050

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Water	Cooler -	Tennis	Courts	
				_

Asset ID

1062

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



1027

Water Coolers

Asset ID

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Community Advisors Page 5-59 March 26, 2021

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the Association can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors, and comparison of similar component cost found at other properties.

The funding plan we develop includes adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. <u>Full Funding</u> provides the best option to avoid deferred maintenance or special assessments. <u>Baseline Funding</u> maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums, and commercial investment properties.

Personal Service attention to detail, quick response, and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street, and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. *Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.*

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

Community Advisors Page 6-1 March 26, 2021

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

Community Advisors Page 6-2 March 26, 2021

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.

Community Advisors Page 6-3 March 26, 2021