Reserve Study Update Rolling Hills CDD Green Cove Springs, Florida



Prepared for FY 2022 Report Date: May 25, 2022





May 25, 2022

Mr. Jim Oliver, District Manager Governmental Management Services, LLC 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Rolling Hills CDD

Dear Mr. Oliver:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. At the request of the District no site visit was conducted. We recommend an update with a site visit every three years or sooner if components have been added or removed from the inventory or component damage has occurred.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA.

Once you have reviewed this report and considered recent expenditures and any historic cost data we will make necessary adjustments.

Respectively submitted,

CRShamarl

Charles R. Sheppard *RS PRA CCI* Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275 www.communityadvisors.comm







SPECIAL NOTICE

THIS RESERVE ANALYLSIS INCLUDED A VISUAL OBSERVATION OF MAJOR COMPONENTS FOR YOUR PROPERTY. NO DISTRUCTION TESTING OR OTHER TESTING WAS CONDUCTED TO DETERMINE COMPONENT CONDITION. OUR ANALYSIS INCLUDES COMPONENTS WITH REPLACEMENT COST AND USEFUL LIFE PROJECTIONS THAT ARE TYPICAL FOR THIS TYPE OF FACILITY.

THIS ANALYSIS IS NOT A SAFETY INSPECTION OR STRUCTURAL INSPECTION AND WE RECOMMEND THE ASSOCIATION CONDUCT THOSE INSPECTIONS ON A REGULAR BASIS WITH OTHER CONSULTANTS.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Executive Summary	1-1
Financial Summary - Recommended Funding Plan	1-2
Recommended Funding Plan VS Fully Funded	1-3
Current Funding Plan vs Recommended Funding Plan	1-4
CURRENT FUNDING PLAN	
Financial Summary - Current Funding Plan	2-1
Current Funding Plan vs Fully Funded Plan	2-2
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	4-8
COMPONENT INVENTORY	
Component Inventory	5-1
Component Detail Index	5-4
Component Detail	5-8
DISCLOSURERS & INFORMATION	
Report Navigation	6-1
Methodology & Information	6-2
Terms of Service	6-3
Definitions	6-4

Executive Summary

Account Information

Account Name Rolling Hills CDD Account Number 1651

City Green Cove Springs Last Site Visit March, 4 2021 State Florida Report Date May, 25 2022

In Service Date January, 1 2007 Report Version 1

Total Units Fiscal Year Start October, 1 2022
Study Level Level II Update Fiscal year End September, 30 2023

Reserve Fund Information

Current Component Replacement Cost \$1,407,847

Number of Components 90

Reserve Fund Beginning Balance \$137,651

Billing Term Annually

Component Funding (Straight Line)

Recommended First Year Reserve Fund Contribution \$397,071
Interest Rate on Reserve Deposits 0%
Inflation Rate on Replacement Cost 0%

Pooled Cash (Current Funding Plan)

Current Year Reserve Fund Contribution \$75,000
Interest Rate on Reserve Deposits Variable
Inflation Rate on Replacement Cost Variable
Annual Contribution Increases 1.0%

Pooled Cash (Recommended Funding Plan)

Recommended First Year Reserve Fund Contribution
Interest Rate on Reserve Deposits
Inflation Rate on Replacement Cost
Annual Contribution Increases

\$315,023
Variable
Variable
1.0%


Comments

- Street were removed and component cost updated to current replacement cost.
- Current funding level is not adequate for future component replacement.
- Recommended funding plan requires larger contributions for adequate funding.


Rolling Hills CDD Financial Summary - Recommended Funding Plan

Begining Balance: \$137,651 Fully Funded: \$952,522 Tax Rate:0%

	0	U	. ,		•	,				
	dent	~	_	dia			نگار خ	<i>و</i>	5 8	, so s
Year	A SON	Tallaga de	And South	Ogot Arcoug	An Age	45 Ministra	TO ST THE	To Spanie	28 12 2	रूप राजावे इके राजावे
Tear	~ 0	→ →	V & C	0 \$	→ →	~ ~	~ ~	~ ~	~ ~ ~	
22-23	1,407,847	6.0%	315,023	0	3.50%	10,302	20,676	442,300	1,063,138	42%
23-24	1,492,317	5.0%	184,471	0	0.50%	234	442,300	184,705	738,821	25%
24-25	1,566,933	4.0%	121,494	0	1.00%	1,685		307,885	858,793	36%
25-26	1,629,611	3.0%	122,709	0	1.50%	4,291	6,899	427,986	970,758	44%
26-27	1,678,499	3.0%	123,936	0	2.00%	8,285		560,207	1,095,986	51%
27-28	1,728,854	3.0%	125,176	0	2.50%	13,693		699,076	1,227,854	57%
28-29	1,780,719	3.0%	126,427	0	3.00%	14,647	199,628	640,522	1,161,752	55%
29-30	1,834,141	3.0%	127,692	0	3.50%	22,070		790,284	1,302,363	61%
30-31	1,889,165	3.0%	128,968	0	3.50%	19,601	221,578	717,275	1,222,142	59%
31-32	1,945,840	3.0%	130,258	0	3.50%	24,846		872,379	1,371,006	64%
32-33	2,004,215	3.0%	131,561	0	3.50%	22,067	235,814	790,193	1,284,814	62%
33-34	2,064,342	3.0%	132,876	0	3.50%	19,683	223,049	719,703	1,212,651	59%
34-35	2,126,272	3.0%	134,205	0	3.50%	25,069		878,977	1,371,635	64%
35-36	2,190,060	3.0%	135,547	0	3.50%	10,063	589,352	435,236	932,034	47%
36-37	2,255,762	3.0%	136,903	0	3.50%	11,562	104,148	479,552	982,970	49%
37-38	2,323,435	3.0%	138,272	0	3.50%	14,243	73,224	558,843	1,071,193	52%
38-39	2,393,138	3.0%	139,654	0	3.50%	1,274	524,437	175,336	701,339	25%
39-40	2,464,932	3.0%	141,051	0	3.50%	6,256		322,642	864,704	37%
40-41	2,538,880	3.0%	142,461	0	3.50%	11,461		476,565	1,037,240	46%
41-42	2,615,047	3.0%	143,886	0	3.50%	16,898		637,349	1,219,350	52%
42-43	2,693,498	3.0%	145,325	0	3.50%	21,191	39,557	764,307	1,370,709	56%
43-44	2,774,303	3.0%	146,778	0	3.50%	24,780	65,424	870,442	1,504,631	58%
44-45	2,857,532	3.0%	148,246	0	3.50%	27,483	95,821	950,350	1,616,069	59%
45-46	2,943,258	3.0%	149,728	0	3.50%	33,685		1,133,763	1,834,494	62%
46-47	3,031,556	3.0%	151,226	0	3.50%	40,157		1,325,146	2,064,571	64%
47-48	3,122,502	3.0%	152,738	0	3.50%	17,499	840,274	655,108	1,441,319	45%
48-49	3,216,177	3.0%	154,265	0	3.50%	13,546	284,706	538,213	1,377,013	39%
49-50	3,312,663	3.0%	155,808	0	3.50%	18,982	14,024	698,979	1,595,151	44%
50-51	3,412,043	3.0%	157,366	0	3.50%	25,154		881,499	1,840,017	48%
51-52	3,514,404	3.0%	158,940	0	3.50%	28,242	95,880	972,801	1,999,383	49%



The recommended funding plan provides adequate funding with moderate contributions over time.




This chart illustrates annual expenditures and compares the current funding plan to the recommended funding plan.

Rolling Hills CDD Financial Summary - Current Funding Plan

Begining Balance: \$137,651 Fully Funded: \$952,522 Tax Rate:0%

	2.0					+ > = -,= ==				
		~	_	ajor .			کان ک	je b	5 8	80 D d
Year	A Constant	क्रिकेट	A SO SO SILI	Ottet tooks	4412	4° 40° 5°			28 LA LA	in things
						4.004				10-1
22-23	1,407,847	6.0%	75,000	0	3.50%	1,901	20,676	193,876	1,063,138	18%
23-24	1,492,317	5.0%	75,750	0	0.50%		442,300	-172,674	738,821	
24-25	1,566,933	4.0%	76,508	0	1.00%			-96,166	858,793	
25-26	1,629,611	3.0%	77,273	0	1.50%		6,899	-25,793	970,758	
26-27	1,678,499	3.0%	78,045	0	2.00%			52,253	1,095,986	5%
27-28	1,728,854	3.0%	78,826	0	2.50%			131,078	1,227,854	11%
28-29	1,780,719	3.0%	79,614	0	3.00%		199,628	11,064	1,161,752	1%
29-30	1,834,141	3.0%	80,410	0	3.50%			91,475	1,302,363	7%
30-31	1,889,165	3.0%	81,214	0	3.50%		221,578	-48,889	1,222,142	
31-32	1,945,840	3.0%	82,026	0	3.50%			33,138	1,371,006	2%
32-33	2,004,215	3.0%	82,847	0	3.50%		235,814	-119,829	1,284,814	
33-34	2,064,342	3.0%	83,675	0	3.50%		223,049	-259,204	1,212,651	
34-35	2,126,272	3.0%	84,512	0	3.50%			-174,692	1,371,635	
35-36	2,190,060	3.0%	85,357	0	3.50%		589,352	-678,686	932,034	
36-37	2,255,762	3.0%	86,211	0	3.50%		104,148	-696,624	982,970	
37-38	2,323,435	3.0%	87,073	0	3.50%		73,224	-682,775	1,071,193	
38-39	2,393,138	3.0%	87,943	0	3.50%		524,437	-1,119,268	701,339	
39-40	2,464,932	3.0%	88,823	0	3.50%			-1,030,446	864,704	
40-41	2,538,880	3.0%	89,711	0	3.50%			-940,734	1,037,240	
41-42	2,615,047	3.0%	90,608	0	3.50%			-850,126	1,219,350	
42-43	2,693,498	3.0%	91,514	0	3.50%		39,557	-798,169	1,370,709	
43-44	2,774,303	3.0%	92,429	0	3.50%		65,424	-771,164	1,504,631	
44-45	2,857,532	3.0%	93,354	0	3.50%		95,821	-773,631	1,616,069	
45-46	2,943,258	3.0%	94,287	0	3.50%			-679,344	1,834,494	
46-47	3,031,556	3.0%	95,230	0	3.50%			-584,114	2,064,571	
47-48	3,122,502	3.0%	96,182	0	3.50%		840,274	-1,328,206	1,441,319	
48-49	3,216,177	3.0%	97,144	0	3.50%		284,706	-1,515,767	1,377,013	
49-50	3,312,663	3.0%	98,116	0	3.50%		14,024	-1,431,676	1,595,151	
50-51	3,412,043	3.0%	99,097	0	3.50%			-1,332,579	1,840,017	
51-52	3,514,404	3.0%	100,088	0	3.50%		95,880	-1,328,371	1,999,383	



	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Beginning Balance	137,651	442,300	184,705	307,885	427,986	560,207	699,076	640,522	790,284	717,275
Annual Assessment	315,023	184,471	121,494	122,709	123,936	125,176	126,427	127,692	128,968	130,258
Interest Earned	10,302	234	1,685	4,291	8,285	13,693	14,647	22,070	19,601	24,846
Expenditures	20,676	442,300		6,899			199,628		221,578	
Fully Funded Reserves	1,063,138	738,821	858,793	970,758	1,095,986	1,227,854	1,161,752	1,302,363	1,222,142	1,371,006
Percent Fully Funded	42%	25%	36%	44%	51%	57%	55%	61%	59%	64%
Ending Balance	442,300	184,705	307,885	427,986	560,207	699,076	640,522	790,284	717,275	872,379

Description

Misc. Site Components

Concrete Pavers - Entry

Concrete Pavers - Resident's Club

Mail Box Pedestals Street Signs/Poles

Wood Boardwalk Frame/Rails/Deck (not pilings)

Misc. Site Components Total:

Parking Lot Resurfacing

Asphalt Mill/Overlay 1 1/2" - Parking Lot

Parking Lot Resurfacing Total: 129,781

Site Lighting

Decorative Light Poles - Amenity

Light Poles Shoebox Fixtures - Tennis Courts

Site Lighting Total:

Fencing

Aluminum Fence - Pool

Chain Link Fence VC 10 Ft - Tennis Courts

Fencing Total:

Misc. Building Components

Aluminum Gutters/DS - Resident's Club & Pavilion

Refurbishment Allowance - Family Restroom

Refurbishment Allowance - Fitness Locker Rooms

6,577

25,803

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Misc. Building Components continued										
Refurbishment Allowance - Pavilion Restrooms							22,019			
Refurbishment Allowance - Pool Restrooms							45,585			
Vinyl Railings - Porch										
Wood Deck - Porch							2,196			
Misc. Building Components Total:							102,180			
Roofing										
Asphalt Shingles - Pavilion										
Asphalt Shingles - Resident's Club										
Metal Roof - Picnic Pavilion										
Metal Roof - Pool Monitor										
Metal Roof - Resident's Club										
Metal Roof - Tennis Pavilion										
Roofing Total:										
Exterior Painting										
Picnic Pavilion	1,680									
Pool Pavilion	6,156									
Resident's Club	11,160									
Tennis Pavilion	1,680									
Exterior Painting Total:	20,676									
Flooring										
Carpet - Resident's Club Great Room		1,824								
Carpet - Resident's Club Offices		1,903								
Floor Tile - 1st Floor										
Floor Tile - Lobby										
Rubber Flooring - Fitness Room										
Vinyl Flooring - Kids Zone										
Flooring Total:		3,727								

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Cabinets & Tops										
Top/Sink - Pavilion										
Wood Cabinets & SS Tops - Kitchen							3,939			
Wood Cabinets & SS Tops - Reception/Conf. Rm							6,783			
Cabinets & Tops Total:							10,722			
Furniture Fixtures & Equipment										
Appliance Package - Kitchen				4,630						
Fitness Equip. Full Replace Allowance										
Furniture Allowance - Resident's Club							6,324			
Pool/Deck Furniture Full Replacement Allowance									40,256	
Wall Oven Double				2,269						
Furniture Fixtures & Equipment Total:				6,899			6,324		40,256	
HVAC Equipment										
Heat Pump 1 - 10 Ton		16,960								
Heat Pump 2 - 8 Ton		13,568								
Heat Pump 3 - 7 Ton		11,872								
HVAC Equipment Total:		42,400								
Swimming Pool										
Concrete Pavers - Pool										
Fiberglass Refurbishment Allow - Pool Slide		15,900								
Lane Divider Reel										
Lane Dividers		3,371								
Play Equip. Refurbishment Allow - Splash Pool		5,300								
Pool Filtration Refurbishment Allowance										
Pool Lift							8,095			
Pool Resurfacing/Tile Misc Repair		318,170								
Shade Structure Fabric - Pool		12,720								
Shade Structure Frame - Pool							20.404			
Starting Blocks							20,491			
Steel Stair Refurbishment Allowance		255 466					20.507			
Swimming Pool Total:		355,460					28,586			

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description		_ _ -		•		3		_, _,		-
Tennis Courts										
Asphalt Resufacing (color coat) Shade Structure Frame - Tennis Courts		40,713							51,540	
Tennis Courts Total:		40,713							51,540	
Playground										
Park Bench Expanded Metal							3,289			
Plastic Play Surface Border							6,534			
Play Equipment Allowance							37,946			
Swings Two Bay Arched							4,048			
Playground Total:							51,816			
Components Not Included										
Asphalt Seal Coat	Unfunded									
Building Sign	Unfunded									
Ceiling Fans	Unfunded									
Community Signs	Unfunded									
Concrete Curbs/Walks	Unfunded									
Doors/Windows	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Electric Lift	Unfunded									
Fitness Equipment Partial Replace Allowance	Unfunded									
Flag Pole	Unfunded									
Gas Grill	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Light Poles - Parking Lot	Unfunded									
Monument Sign Refurbishment	Unfunded									
Nets/Poles - Tennis Courts	Unfunded									
Pond Fountains/Aerators	Unfunded									
Pool Filtration Partial Replacement	Unfunded									
Pool/Deck Furniture Partial Replacement	Unfunded									
Railings	Unfunded									
Rubber Play Surface - Playground	Unfunded									

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Components Not Included continued										
Shade Structure Fabric - Tennis Courts	Unfunded									
Stormwater Pond Dredging/Pipe/Structures	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines	Unfunded									
Volley Ball Court	Unfunded									
Water Cooler - Tennis Courts	Unfunded									
Water Coolers	Unfunded									
Year Total:	20,676	442,300		6,899			199,628		221,578	

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
n · · · n ·										
Beginning Balance Annual Assessment	872,379 131,561	790,193 132,876	719,703 134,205	878,977 135,547	435,236 136,903	479,552 138,272	558,843 139,654	175,336 141,051	322,642 142,461	476,565 143,886
Interest Earned	22,067	19,683	25,069	10,063	11,562	14,243	1,274	6,256	11,461	16,898
Expenditures	235,814	223,049	20,000	589,352	104,148	73,224	524,437	0,200	11,.01	10,070
Fully Funded Reserves	1,284,814	1,212,651	1,371,635	932,034	982,970	1,071,193	701,339	864,704	1,037,240	1,219,350
Percent Fully Funded	62%	59%	64%	47%	49%	52%	25%	37%	46%	52%
Ending Balance	790,193	719,703	878,977	435,236	479,552	558,843	175,336	322,642	476,565	637,349
Description										
Description Misc. Site Components										
Concrete Pavers - Entry		18,528								
Concrete Pavers - Resident's Club							14,168			
Mail Box Pedestals										
Street Signs/Poles		104000					34,677			
Wood Boardwalk Frame/Rails/Deck (not pilings)		106,982					40.04			
Misc. Site Components Total:		125,510					48,845			
Parking Lot Resurfacing										
Asphalt Mill/Overlay 1 1/2" - Parking Lot										
Parking Lot Resurfacing Total:										
Site Lighting										
Decorative Light Poles - Amenity	47,833									
Light Poles Shoebox Fixtures - Tennis Courts	92,250									
Site Lighting Total:	140,083									
Fencing										
Aluminum Fence - Pool							48,344			
Chain Link Fence VC 10 Ft - Tennis Courts	66,297									
Fencing Total:	66,297						48,344			
Misc. Building Components										
Aluminum Gutters/DS - Resident's Club & Pavilio	n						6,338			
Refurbishment Allowance - Family Restroom							2,220			
Refurbishment Allowance - Fitness Locker Rooms										

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Misc. Building Components continued										
Refurbishment Allowance - Pavilion Restrooms										
Refurbishment Allowance - Pool Restrooms										
Vinyl Railings - Porch							4,581			
Wood Deck - Porch										
Misc. Building Components Total:							10,919			
Roofing										
Asphalt Shingles - Pavilion							33,453			
Asphalt Shingles - Resident's Club							78,982			
Metal Roof - Picnic Pavilion							6,300			
Metal Roof - Pool Monitor							2,648			
Metal Roof - Resident's Club							9,952			
Metal Roof - Tennis Pavilion							7,248			
Roofing Total:							138,585			
Exterior Painting										
Picnic Pavilion	2,392									
Pool Pavilion	8,764									
Resident's Club	15,887									
Tennis Pavilion	2,392									
Exterior Painting Total:	29,434									
Flooring										
Carpet - Resident's Club Great Room				2,676						
Carpet - Resident's Club Offices				2,793						
Floor Tile - 1st Floor							955			
Floor Tile - Lobby							7,109			
Rubber Flooring - Fitness Room		3,285								
Vinyl Flooring - Kids Zone		6,862								
Flooring Total:		10,147		5,469			8,063			

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Cabinets & Tops										
Top/Sink - Pavilion		1,466								
Wood Cabinets & SS Tops - Kitchen										
Wood Cabinets & SS Tops - Reception/Conf. Rm										
Cabinets & Tops Total:		1,466								
Furniture Fixtures & Equipment										
Appliance Package - Kitchen						6,601				
Fitness Equip. Full Replace Allowance					40,057					
Furniture Allowance - Resident's Club										
Pool/Deck Furniture Full Replacement Allowance						2.025				
Wall Oven Double Furniture Fixtures & Equipment Total:					40,057	3,235 9,836				
					40,057	9,030				
HVAC Equipment										
Heat Pump 1 - 10 Ton				24,890						
Heat Pump 2 - 8 Ton				19,912						
Heat Pump 3 - 7 Ton				17,423						
HVAC Equipment Total:				62,224						
Swimming Pool										
Concrete Pavers - Pool							266,110			
Fiberglass Refurbishment Allow - Pool Slide				23,334						
Lane Divider Reel				4.0.45			3,570			
Lane Dividers				4,947						
Play Equip. Refurbishment Allow - Splash Pool Pool Filtration Refurbishment Allowance				7,778	64,091					
Pool Lift					04,091					
Pool Resurfacing/Tile Misc Repair				466,932						
Shade Structure Fabric - Pool				18,667						
Shade Structure Frame - Pool		49,855		,						
Starting Blocks										
Steel Stair Refurbishment Allowance		21,995								
Swimming Pool Total:		71,849		521,658	64,091		269,680			

Description		32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Tennis Courts	Description										-
Asphalt Resufacing (color coat) Shade Structure Frame - Tennis Courts Frame - Tennis Courts Total: 14,077 14,077 14,077 18,070 Playground Park Bench Expanded Metal Plastic Play Surface Border Play Equipment Allowance Swings Two Bay Arched Playeround Components Not Included Asphalt Seal Coat Building Sign Unfunded Colling Fans Concrete Curbs-Walks Unfunded Concrete Curbs-Walks Unfunded Dournster Elcosure/Gates Electric Lift Urfunded Fitness Equipment Partial Replace Allowance Fitness Equipment Partial Replace Allowance Unfunded Gas Grill Light Poles - Parking Lot Unfunded Unfunded Unfunded Unfunded Unfunded Fitness Equipment Partial Replace Allowance Unfunded Unfunded Unfunded Fitness Equipment Partial Replace Allowance Unfunded Fitness Equipment Partial Replace Allowance Unfunded Fitness Equipment System Unfunded Unfunded Unfunded Unfunded Light Poles - Parking Lot Unfunded											
Shade Structure Frame - Tennis Courts Total: 14,077 63,388 Playground Park Bench Expanded Metal Plastic Play Surface Border Play Equipment Allowance Swings Two Bay Arched Playground Total: Components Not Included Asphalt Scal Coat Building Sign Unfunded Ceiling Fans Unfunded Community Signs Unfunded Concret Curbs/Walks Unfunded Doors/Windows Unfunded Electric Lift Fitness Equipment Partial Replace Allowance Playground System Unfunded Gas Grill Irrigation System Unfunded Landscaping Unfunded Landscaping Landscaping Unfunded Monument Sign Refurbishment Minfunded Fitness Facily Refurbishment Unfunded Unfunded Unfunded Unfunded Landscaping Landscaping Landscaping Unfunded Monument Sign Refurbishment Unfunded Fitness Facily Refurbishment Unfunded Unfunded Unfunded Unfunded Landscaping Landscaping Unfunded Monument Sign Refurbishment Unfunded Unfunded Monument Sign Refurbishment Unfunded Mo							63 388				
Tennis Courts Total: Playground Park Bench Expanded Metal Plastic Play Surface Border Play Equipment Allowance Swings Two Bay Arched Playground Total: Components Not Included Asphalt Seal Coat Unfunded Building Sign Unfunded Colling Fans Unfunded Community Signs Unfunded Conrece Curbs/Walks Unfunded Dumpster Enclosure/Gates Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Unfunded Fitness Equipment Partial Replace Allowance Unfunded Lingtation System Unfunded Lingtation System Unfunded Lingtation System Unfunded Lingth Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Monument Sign R			14.077				05,500				
Park Bench Expanded Metal Plastic Play Surface Border Play Equipment Allowance Swings Two Bay Arched Playground Total: Components Not Included Asphalt Seal Coat Unfunded Building Sign Unfunded Building Fans Unfunded Community Signs Unfunded Community Signs Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Doumpster Enclosure/Gates Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Fitagion System Unfunded Gas Grill Irrigation System Unfunded Irrigation System Unfunded Lught poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Monument Sign Refurbishment Unfunded Monument Sign Refurbishment Unfunded Fool Floes - Parking Lot Unfunded Fool Flores - Parking Lot Unfunded Flores - Parking Lot							63,388				
Park Bench Expanded Metal Plastic Play Surface Border Play Equipment Allowance Swings Two Bay Arched Playground Total: Components Not Included Asphalt Seal Coat Unfunded Building Sign Unfunded Building Fans Unfunded Community Signs Unfunded Community Signs Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Doumpster Enclosure/Gates Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Fitagion System Unfunded Gas Grill Irrigation System Unfunded Irrigation System Unfunded Lught poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Monument Sign Refurbishment Unfunded Monument Sign Refurbishment Unfunded Fool Floes - Parking Lot Unfunded Fool Flores - Parking Lot Unfunded Flores - Parking Lot	Playground										
PlayEquipment Allowance Swings Two Bay Arched Playground Total: Components Not Included Asphalt Scal Coat	• •										
Play Equipment Allowance Swings Two Bay Arched Playground Total: Components Not Included Asphalt Seal Coat Unfunded Building Sign Unfunded Ceiling Fans Unfunded Community Signs Unfunded Community Signs Unfunded Community Signs Unfunded Consylvindows											
Playground Total: Components Not Included Asphalt Seal Coat Building Sign Unfunded Celling Fans Unfunded Community Signs Unfunded Community Signs Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Dournyster Enclosure/Gates Unfunded Electric Lift Unfunded Electric Lift Unfunded Gas Grill Irrigation System Unfunded Unfunded Unfunded Irrigation System Unfunded Light Poles - Parking Lot Monument Sign Refurbishment Unfunded Pond Fountains/Aerators Unfunded Pool/Deck Furniar Courts Unfunded Pool/Deck Furniar Replacement Unfunded Unfunded Vinfunded											
Components Not Included Asphalt Seal Coat Unfunded Building Sign Unfunded Ceiling Fans Unfunded Community Signs Unfunded Community Signs Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Doors/Windows Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Flag Pole Unfunded Fitness Equipment Partial Replace Allowance Unfunded Fitness Equipment Partial Replace Allowance Unfunded Gas Grill Unfunded Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Nets/Poles - Tennis Courts Unfunded Nets/Poles - Tennis Courts Unfunded Pool Flurtation Partial Replacement Unfunded Nets/Poles - Tennis Courts Unfunded Nets/Poles - Tennis Courts Unfunded Nets/Poles - Tennis Courts Unfunded Pool Flitration Partial Replacement Unfunded Pool Flitration Partial Replacement Unfunded Railings Unfunded Vufunded Vufunded Vufunded Vufunded	Swings Two Bay Arched										
Asphalt Seal Coat Unfunded Building Sign Unfunded Ceiling Fans Unfunded Community Signs Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Dompster Enclosure/Gates Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Unfunded Fitness Equipment Partial Replace Allowance Unfunded Irrigation System Unfunded Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Nets/Poles - Tennis Courts Unfunded Nets/Poles - Tennis Courts Unfunded Pond Fountains/Aerators Unfunded Pool Flutation Partial Replacement Unfunded Pool Flutation Partial Replacement Unfunded Railings Unfunded Railings Unfunded	•										
Asphalt Seal Coat Unfunded Building Sign Unfunded Ceiling Fans Unfunded Community Signs Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Dompster Enclosure/Gates Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Unfunded Fitness Equipment Partial Replace Allowance Unfunded Irrigation System Unfunded Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Nets/Poles - Tennis Courts Unfunded Nets/Poles - Tennis Courts Unfunded Pond Fountains/Aerators Unfunded Pool Flutation Partial Replacement Unfunded Pool Flutation Partial Replacement Unfunded Railings Unfunded Railings Unfunded	Components Not Included										
Building Sign Unfunded Cciling Fans Unfunded Community Signs Unfunded Comcret Curbs/Walks Unfunded Concrete Curbs/Walks Unfunded Doors/Windows Unfunded Dumpster Enclosure/Gates Unfunded Electric Lift Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Infunded Gas Grill Unfunded Irrigation System Unfunded Irrigation System Unfunded Landscaping Unfunded Landscaping Unfunded Monument Sign Refurbishment Unfunded Monument Sign Refurbishment Unfunded Pool Foles - Tennis Courts Unfunded Nets/Poles - Tennis Courts Unfunded Pool Filtration Partial Replacement Unfunded Pool Filtration Partial Replacement Unfunded Railings Unfunded Unfunded Unfunded		Unfunded									
Ceiling FansUnfundedCommunity SignsUnfundedConcrete Curbs/WalksUnfundedDoors/WindowsUnfundedDumpster Enclosure/GatesUnfundedElectric LiftUnfundedFitness Equipment Partial Replace AllowanceUnfundedFlag PoleUnfundedGas GrillUnfundedIrrigation SystemUnfundedLandscapingUnfundedLight Poles - Parking LotUnfundedMonument Sign RefurbishmentUnfundedNets/Poles - Tennis CourtsUnfundedPool Flitration Partial ReplacementUnfundedPool Fountains/AeratorsUnfundedPool/Deck Furniture Partial ReplacementUnfundedRailingsUnfunded											
Concrete Curbs/Walks Doors/Windows Unfunded Dumpster Enclosure/Gates Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Flag Pole Gas Grill Unfunded Irrigation System Unfunded Light Poles - Parking Lot Monument Sign Refurbishment Nets/Poles - Tennis Courts Vnfunded Nots/Poles - Tennis Courts Vnfunded Pool Fountains/Aerators Unfunded Pool Fountains/Aerators Unfunded Pool/Deck Furniture Partial Replacement Unfunded Railings Unfunded Unfunded Unfunded Unfunded Unfunded Pool/Deck Furniture Partial Replacement Unfunded Unfunded Pool/Deck Furniture Partial Replacement Unfunded Unfunded		Unfunded									
Doors/WindowsUnfundedDumpster Enclosure/GatesUnfundedElectric LiftUnfundedFitness Equipment Partial Replace AllowanceUnfundedFlag PoleUnfundedGas GrillUnfundedIrrigation SystemUnfundedLandscapingUnfundedLight Poles - Parking LotUnfundedMonument Sign RefurbishmentUnfundedNets/Poles - Tennis CourtsUnfundedPond Fountains/AeratorsUnfundedPool Filtration Partial ReplacementUnfundedPool/Deck Furniture Partial ReplacementUnfundedRailingsUnfunded	Community Signs	Unfunded									
Dumpster Enclosure/Gates Unfunded Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Flag Pole Unfunded Gas Grill Unfunded Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Monument Sign Refurbishment Unfunded Pond Fountains/Aerators Unfunded Pond Fountains/Aerators Unfunded Pool/Deck Furniture Partial Replacement Unfunded Railings Unfunded Ponfunded Ponfunded Pool/Deck Furniture Partial Replacement Unfunded Railings Unfunded	Concrete Curbs/Walks	Unfunded									
Electric Lift Unfunded Fitness Equipment Partial Replace Allowance Flag Pole Unfunded Gas Grill Unfunded Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Nets/Poles - Tennis Courts Unfunded Pool Fountains/Aerators Unfunded Pool Filtration Partial Replacement Unfunded Railings Unfunded Runded Pool/Deck Furniture Partial Replacement Unfunded Runded Runded Pool/Deck Furniture Partial Replacement Unfunded Runded Ru	Doors/Windows	Unfunded									
Fitness Equipment Partial Replace Allowance Flag Pole Gas Grill Irrigation System Unfunded Landscaping Unfunded Light Poles - Parking Lot Monument Sign Refurbishment Nets/Poles - Tennis Courts Unfunded Pond Fountains/Aerators Unfunded Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Unfunded Unfunded Unfunded Unfunded Unfunded Unfunded	Dumpster Enclosure/Gates	Unfunded									
Flag Pole Gas Grill Irrigation System Unfunded Landscaping Light Poles - Parking Lot Monument Sign Refurbishment Vunfunded Nets/Poles - Tennis Courts Vunfunded Pond Fountains/Aerators Vunfunded Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded	Electric Lift	Unfunded									
Gas Grill Irrigation System Unfunded Landscaping Light Poles - Parking Lot Monument Sign Refurbishment Nets/Poles - Tennis Courts Vunfunded Pond Fountains/Aerators Vunfunded Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded Vunfunded	Fitness Equipment Partial Replace Allowance	Unfunded									
Irrigation System Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Nets/Poles - Tennis Courts Unfunded Pond Fountains/Aerators Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Unfunded Unfunded Unfunded	Flag Pole	Unfunded									
Landscaping Unfunded Light Poles - Parking Lot Unfunded Monument Sign Refurbishment Unfunded Nets/Poles - Tennis Courts Unfunded Pond Fountains/Aerators Unfunded Pool Filtration Partial Replacement Unfunded Pool/Deck Furniture Partial Replacement Unfunded Railings Unfunded	Gas Grill	Unfunded									
Light Poles - Parking Lot Monument Sign Refurbishment Vufunded Nets/Poles - Tennis Courts Pond Fountains/Aerators Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Unfunded Unfunded	Irrigation System	Unfunded									
Monument Sign Refurbishment Nets/Poles - Tennis Courts Pond Fountains/Aerators Pool Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Unfunded Unfunded Unfunded	Landscaping	Unfunded									
Nets/Poles - Tennis Courts Pond Fountains/Aerators Pond Filtration Partial Replacement Pool/Deck Furniture Partial Replacement Railings Unfunded Unfunded Unfunded	Light Poles - Parking Lot	Unfunded									
Pond Fountains/Aerators Unfunded Pool Filtration Partial Replacement Unfunded Pool/Deck Furniture Partial Replacement Unfunded Unfunded Railings Unfunded	Monument Sign Refurbishment	Unfunded									
Pool Filtration Partial Replacement Unfunded Pool/Deck Furniture Partial Replacement Unfunded Railings Unfunded	Nets/Poles - Tennis Courts	Unfunded									
Pool/Deck Furniture Partial Replacement Unfunded Railings Unfunded	Pond Fountains/Aerators	Unfunded									
Railings Unfunded	Pool Filtration Partial Replacement	Unfunded									
	Pool/Deck Furniture Partial Replacement	Unfunded									
Rubber Play Surface - Playground Unfunded	Railings	Unfunded									
	Rubber Play Surface - Playground	Unfunded									

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Components Not Included continued										
Shade Structure Fabric - Tennis Courts	Unfunded									
Stormwater Pond Dredging/Pipe/Structures	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines	Unfunded									
Volley Ball Court	Unfunded									
Water Cooler - Tennis Courts	Unfunded									
Water Coolers	Unfunded									
Year Total:	235,814	223,049		589,352	104,148	73,224	524,437			

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Beginning Balance	637,349	764,307	870,442	950,350	1,133,763	1,325,146	655,108	538,213	698,979	881,499
Annual Assessment	145,325	146,778	148,246	149,728	151,226	152,738	154,265	155,808	157,366	158,940
Interest Earned	21,191	24,780	27,483	33,685	40,157	17,499	13,546	18,982	25,154	28,242
Expenditures	39,557	65,424	95,821			840,274	284,706	14,024		95,880
Fully Funded Reserves	1,370,709	1,504,631	1,616,069	1,834,494	2,064,571	1,441,319	1,377,013	1,595,151	1,840,017	1,999,383
Percent Fully Funded	56%	58%	59%	62%	64%	45%	39%	44%	48%	49%
Ending Balance	764,307	870,442	950,350	1,133,763	1,325,146	655,108	538,213	698,979	881,499	972,801

Description

Misc. Site Components

Concrete Pavers - Entry

Concrete Pavers - Resident's Club

Mail Box Pedestals 17,862

Street Signs/Poles

Wood Boardwalk Frame/Rails/Deck (not pilings)

Misc. Site Components Total: 17,862

Parking Lot Resurfacing

Asphalt Mill/Overlay 1 1/2" - Parking Lot

Parking Lot Resurfacing Total:

Site Lighting

Decorative Light Poles - Amenity

Light Poles Shoebox Fixtures - Tennis Courts

Site Lighting Total:

Fencing

Aluminum Fence - Pool

Chain Link Fence VC 10 Ft - Tennis Courts

Fencing Total:

Misc. Building Components

Aluminum Gutters/DS - Resident's Club & Pavilion

Refurbishment Allowance - Family Restroom

11,879

Refurbishment Allowance - Fitness Locker Rooms

46,603

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Misc. Building Components continued										
Refurbishment Allowance - Pavilion Restrooms							39,768			
Refurbishment Allowance - Pool Restrooms							82,332			
Vinyl Railings - Porch										
Wood Deck - Porch							3,966			
Misc. Building Components Total:							184,548			
Roofing										
Asphalt Shingles - Pavilion										
Asphalt Shingles - Resident's Club										
Metal Roof - Picnic Pavilion										
Metal Roof - Pool Monitor										
Metal Roof - Resident's Club										
Metal Roof - Tennis Pavilion										
Roofing Total:										
Exterior Painting										
Picnic Pavilion	3,214									
Pool Pavilion	11,778									
Resident's Club	21,351									
Tennis Pavilion	3,214									
Exterior Painting Total:	39,557									
Flooring										
Carpet - Resident's Club Great Room						3,816				
Carpet - Resident's Club Offices						3,982				
Floor Tile - 1st Floor										
Floor Tile - Lobby										
Rubber Flooring - Fitness Room										
Vinyl Flooring - Kids Zone										
Flooring Total:						7,797				

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Cabinets & Tops										
Top/Sink - Pavilion							7.114			
Wood Cabinets & SS Tops - Kitchen Wood Cabinets & SS Tops - Recention/Conf. Pro-							7,114 12,252			
Wood Cabinets & SS Tops - Reception/Conf. Rm Cabinets & Tops Total:							12,252 19,365			
•							17,505			
Furniture Fixtures & Equipment										
Appliance Package - Kitchen								9,412		
Fitness Equip. Full Replace Allowance							11 400			
Furniture Allowance - Resident's Club Pool/Deck Furniture Full Replacement Allowance							11,422			
Wall Oven Double								4,612		
Furniture Fixtures & Equipment Total:							11,422	14,024		
							,	,-		
HVAC Equipment						25 497				
Heat Pump 1 - 10 Ton Heat Pump 2 - 8 Ton						35,487 28,389				
Heat Pump 3 - 7 Ton						24,841				
HVAC Equipment Total:						88,717				
						,				
Swimming Pool Concrete Pavers - Pool										
Fiberglass Refurbishment Allow - Pool Slide						33,269				
Lane Divider Reel						33,207				
Lane Dividers						7,053				
Play Equip. Refurbishment Allow - Splash Pool						11,090				
Pool Filtration Refurbishment Allowance										
Pool Lift							14,621			
Pool Resurfacing/Tile Misc Repair Shade Structure Fabric - Pool						665,733				
Shade Structure Fabric - Pool Shade Structure Frame - Pool						26,615				
Starting Blocks							37,008			
Steel Stair Refurbishment Allowance							27,000			
Swimming Pool Total:						743,760	51,629			
-						•	•			

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description	_			-		-	-			
Tennis Courts										
Asphalt Resufacing (color coat) Shade Structure Frame - Tennis Courts			77,959							95,880
Tennis Courts Total:			77,959							95,880
Playground										
Park Bench Expanded Metal							5,940			
Plastic Play Surface Border							11,802			
Play Equipment Allowance		59,118								
Swings Two Bay Arched		6,306								
Playground Total:		65,424					17,741			
Components Not Included										
Asphalt Seal Coat	Unfunded									
Building Sign	Unfunded									
Ceiling Fans	Unfunded									
Community Signs	Unfunded									
Concrete Curbs/Walks	Unfunded									
Doors/Windows	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Electric Lift	Unfunded									
Fitness Equipment Partial Replace Allowance	Unfunded									
Flag Pole	Unfunded									
Gas Grill	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Light Poles - Parking Lot	Unfunded									
Monument Sign Refurbishment	Unfunded									
Nets/Poles - Tennis Courts	Unfunded									
Pond Fountains/Aerators	Unfunded									
Pool Filtration Partial Replacement	Unfunded									
Pool/Deck Furniture Partial Replacement	Unfunded									
Railings	Unfunded									
Rubber Play Surface - Playground	Unfunded									

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Components Not Included continued										
Shade Structure Fabric - Tennis Courts	Unfunded									
Stormwater Pond Dredging/Pipe/Structures	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines	Unfunded									
Volley Ball Court	Unfunded									
Water Cooler - Tennis Courts	Unfunded									
Water Coolers	Unfunded									
Year Total:	39,557	65,424	95,821			840,274	284,706	14,024		95,880

Description	Expenditures
Replacement Year 22-23	
Exterior Painting	
Picnic Pavilion	1,680
Pool Pavilion	6,156
Resident's Club	11,160
Tennis Pavilion	1,680
Total for 2022 - 2023	\$20,676
Replacement Year 23-24	
Flooring	
Carpet - Resident's Club Great Room	1,824
Carpet - Resident's Club Offices	1,903
HVAC Equipment	
Heat Pump 1 - 10 Ton	16,960
Heat Pump 2 - 8 Ton	13,568
Heat Pump 3 - 7 Ton	11,872
Swimming Pool	
Fiberglass Refurbishment Allow - Pool Slide	15,900
Lane Dividers	3,371
Play Equip. Refurbishment Allow - Splash Pool	5,300
Pool Resurfacing/Tile Misc Repair	318,170
Shade Structure Fabric - Pool	12,720
Tennis Courts	
Asphalt Resufacing (color coat)	40,713
Total for 2023 - 2024	\$442,300
No Replacement in 24-25	
Replacement Year 25-26	
Furniture Fixtures & Equipment	
Appliance Package - Kitchen	4,630
Wall Oven Double	2,269
Total for 2025 - 2026	\$6,899

No Replacement in 26-27

Description	Expenditures
No Replacement in 27-28	
Replacement Year 28-29	
Misc. Building Components	6.577
Refurbishment Allowance - Family Restroom	6,577
Refurbishment Allowance - Fitness Locker Rooms Refurbishment Allowance - Pavilion Restrooms	25,803
Refurbishment Allowance - Pavilion Restrooms Refurbishment Allowance - Pool Restrooms	22,019 45,585
Wood Deck - Porch	2,196
	2,170
Cabinets & Tops Wood Cabinets & SS Tops Witchen	2 020
Wood Cabinets & SS Tops - Kitchen Wood Cabinets & SS Tops - Reception/Conf. Rm	3,939 6 783
• •	6,783
Furniture Fixtures & Equipment Furniture Allowance - Resident's Club	6.224
	6,324
Swimming Pool	0.007
Pool Lift	8,095
Starting Blocks	20,491
Playground	
Park Bench Expanded Metal	3,289
Plastic Play Surface Border	6,534
Play Equipment Allowance	37,946
Swings Two Bay Arched	4,048
Total for 2028 - 2029	\$199,628
No Replacement in 29-30	
Replacement Year 30-31	
Parking Lot Resurfacing	
Asphalt Mill/Overlay 1 1/2" - Parking Lot	129,781
Furniture Fixtures & Equipment	
Pool/Deck Furniture Full Replacement Allowance	40,256
Tennis Courts	
Asphalt Resufacing (color coat)	51,540
Total for 2030 - 2031	\$221,578
10tai 10t 2030 - 2031	φ441,5/δ

Description	Expenditures
No Replacement in 31-32	
Replacement Year 32-33	
Site Lighting	
Decorative Light Poles - Amenity	47,833
Light Poles Shoebox Fixtures - Tennis Courts	92,250
Fencing	
Chain Link Fence VC 10 Ft - Tennis Courts	66,297
Exterior Painting	
Picnic Pavilion	2,392
Pool Pavilion	8,764
Resident's Club	15,887
Tennis Pavilion	2,392
Total for 2032 - 2033	\$235,814
Donle coment Veer 22 24	
Replacement Year 33-34	
Misc. Site Components	10.520
Concrete Pavers - Entry Wood Pagedyn III Frame (Pagila/Dack (not nilings))	18,528
Wood Boardwalk Frame/Rails/Deck (not pilings)	106,982
Flooring	2.205
Rubber Flooring - Fitness Room	3,285
Vinyl Flooring - Kids Zone	6,862
Cabinets & Tops	1 466
Top/Sink - Pavilion	1,466
Swimming Pool	40.055
Shade Structure Frame - Pool	49,855
Steel Stair Refurbishment Allowance	21,995
Tennis Courts	14.055
Shade Structure Frame - Tennis Courts	14,077
Total for 2033 - 2034	\$223,049
No Replacement in 34-35	
Replacement Year 35-36	
Flooring	
Carpet - Resident's Club Great Room	2,676

Description	Expenditures
Replacement Year 35-36 continued	
Carpet - Resident's Club Offices	2,793
HVAC Equipment	
Heat Pump 1 - 10 Ton	24,890
Heat Pump 2 - 8 Ton	19,912
Heat Pump 3 - 7 Ton	17,423
Swimming Pool	
Fiberglass Refurbishment Allow - Pool Slide	23,334
Lane Dividers	4,947
Play Equip. Refurbishment Allow - Splash Pool	7,778
Pool Resurfacing/Tile Misc Repair	466,932
Shade Structure Fabric - Pool	18,667
Total for 2035 - 2036	\$589,352
Replacement Year 36-37	
Furniture Fixtures & Equipment	
Fitness Equip. Full Replace Allowance	40,057
Swimming Pool	
Pool Filtration Refurbishment Allowance	64,091
Total for 2036 - 2037	\$104,148
Replacement Year 37-38	
Furniture Fixtures & Equipment	
Appliance Package - Kitchen	6,601
Wall Oven Double	3,235
Tennis Courts	
Asphalt Resufacing (color coat)	63,388
Total for 2037 - 2038	\$73,224
Replacement Year 38-39	
Misc. Site Components	
Concrete Pavers - Resident's Club	14,168
Street Signs/Poles	34,677
Fencing	
Aluminum Fence - Pool	48,344
	,


Description	Expenditures
Replacement Year 38-39 continued	
Misc. Building Components	
Aluminum Gutters/DS - Resident's Club & Pavilion	6,338
Vinyl Railings - Porch	4,581
Roofing	
Asphalt Shingles - Pavilion	33,453
Asphalt Shingles - Resident's Club	78,982
Metal Roof - Picnic Pavilion	6,300
Metal Roof - Pool Monitor	2,648
Metal Roof - Resident's Club	9,952
Metal Roof - Tennis Pavilion	7,248
Flooring	
Floor Tile - 1st Floor	955
Floor Tile - Lobby	7,109
Swimming Pool	
Concrete Pavers - Pool	266,110
Lane Divider Reel	3,570
Total for 2038 - 2039	\$524,437
No Replacement in 39-40	
No Replacement in 40-41	
No Replacement in 41-42	
Replacement Year 42-43	
Exterior Painting	
Picnic Pavilion	3,214
Pool Pavilion	11,778
Resident's Club	21,351
Tennis Pavilion	3,214
Total for 2042 - 2043	\$39,557
Replacement Year 43-44	
Playground	
Play Equipment Allowance	59,118
Swings Two Bay Arched	6,306
Total for 2043 - 2044	\$65,424

Description	Expenditures
Replacement Year 44-45	
Misc. Site Components	
Mail Box Pedestals	17,862
Tennis Courts	
Asphalt Resufacing (color coat)	77,959
Total for 2044 - 2045	\$95,821
No Replacement in 45-46	
No Replacement in 46-47	
Replacement Year 47-48	
Flooring	
Carpet - Resident's Club Great Room	3,816
Carpet - Resident's Club Offices	3,982
HVAC Equipment	
Heat Pump 1 - 10 Ton	35,487
Heat Pump 2 - 8 Ton	28,389
Heat Pump 3 - 7 Ton	24,841
Swimming Pool	
Fiberglass Refurbishment Allow - Pool Slide	33,269
Lane Dividers	7,053
Play Equip. Refurbishment Allow - Splash Pool	11,090
Pool Resurfacing/Tile Misc Repair	665,733
Shade Structure Fabric - Pool	26,615
Total for 2047 - 2048	\$840,274
Replacement Year 48-49	
Misc. Building Components	
Refurbishment Allowance - Family Restroom	11,879
Refurbishment Allowance - Fitness Locker Rooms	46,603
Refurbishment Allowance - Pavilion Restrooms	39,768
Refurbishment Allowance - Pool Restrooms	82,332
Wood Deck - Porch	3,966
Cabinets & Tops	
Wood Cabinets & SS Tops - Kitchen	7,114

Description	Expenditures
Replacement Year 48-49 continued Wood Cabinets & SS Tops - Reception/Conf. Rm	12,252
Furniture Fixtures & Equipment Furniture Allowance - Resident's Club	11,422
Swimming Pool	
Pool Lift	14,621
Starting Blocks	37,008
Playground	
Park Bench Expanded Metal	5,940
Plastic Play Surface Border	11,802
Total for 2048 - 2049	\$284,706
Replacement Year 49-50	
Furniture Fixtures & Equipment	
Appliance Package - Kitchen	9,412
Wall Oven Double	4,612
Total for 2049 - 2050	\$14,024
No Replacement in 50-51	
Replacement Year 51-52	
Tennis Courts	
Asphalt Resufacing (color coat)	95,880
Total for 2051 - 2052	\$95,880

Rolling Hills CDD

Green Cove Springs, Florida Asset Current Cost by Category



Rolling Hills CDD Component Inventory

		a d	ROTE		gent .	id ² o		χ.
Description	On Sol	50 76 50 2000	gent Jest	i di	Service Servic	Jili ^s	Jä oš	Caronia Caronia
Misc. Site Components								
Concrete Pavers - Entry	2009	33-34	25	0	11	1,560 Square Feet	8.10	12,636
Concrete Pavers - Resident's Club	2009	38-39	30	0	16	1,029 Square Feet	8.10	8,335
Mail Box Pedestals	2020	44-45	25	0	22	4 Each	2,200.00	8,800
Street Signs/Poles	2009	38-39	30	0	16	17 Each	1,200.00	20,400
Wood Boardwalk Frame/Rails/Deck (not pil Misc. Site Components - Total	12009	33-34	25	0	11	2,280 Square Feet	32.00	72,960 \$123,131
								+,
Parking Lot Resurfacing								
Asphalt Mill/Overlay 1 1/2" - Parking Lot	2009	30-31	22	0	8	5,623 Square Yards	17.20	96,716
Parking Lot Resurfacing - Total								\$96,716
Site Lighting								
Decorative Light Poles - Amenity	2009	32-33	24	0	10	16 Each	2,100.00	33,600
Light Poles Shoebox Fixtures - Tennis Court		32-33	24	0	10	36 Each	1,800.00	_64,800
Site Lighting - Total								\$98,400
Foncing								
Fencing Aluminum Fence - Pool	2009	38-39	30	0	16	790 Lineal Feet	36.00	28,440
Chain Link Fence VC 10 Ft - Tennis Courts		32-33	24	0	10	1,386 Lineal Feet	33.60	46,570
Fencing - Total	2007	32 33	2.	Ü	10	1,500 Emedi i eet	33.00	\$75,010
Misc. Building Components								
Aluminum Gutters/DS - Resident's Club & .		38-39	30	0	16	362 Lineal Feet	10.30	3,729
Refurbishment Allowance - Family Restroor		28-29	20	0	6	2 Each	2,600.00	5,200
Refurbishment Allowance - Fitness Locker.		28-29	20	0	6	300 Square Feet	68.00	20,400
Refurbishment Allowance - Pavilion Restrooms Refurbishment Allowance - Pool Restrooms	2009	28-29 28-29	20 20	0	6 6	256 Square Feet 530 Square Feet	68.00 68.00	17,408 36,040
Vinyl Railings - Porch	2009	38-39	30	0	16	49 Lineal Feet	55.00	2,695
Wood Deck - Porch	2009	28-29	20	0	6	248 Square Feet	7.00	1,736
Misc. Building Components - Total	2007	20 2)	20	Ü	O	2 to square rect	7.00	\$87,208
8 - F								, ,
Roofing								
Asphalt Shingles - Pavilion	2009	38-39	30	0	16	41 Squares	480.00	19,680
Asphalt Shingles - Resident's Club	2009	38-39	30	0	16	96 Squares	484.00	46,464
Metal Roof - Picnic Pavilion	2009	38-39	30	0	16	452 Square Feet	8.20	3,706
Metal Roof - Pool Monitor	2009	38-39	30	0	16	190 Square Feet	8.20	1,558
Metal Roof - Resident's Club	2009	38-39	30	0	16	714 Square Feet	8.20	5,855
Metal Roof - Tennis Pavilion	2009	38-39	30	0	16	520 Square Feet	8.20	4,264
Roofing - Total								\$81,527
Exterior Painting								
Picnic Pavilion	2009	22-23	10	0	0	1 Lump Sum	1,680.00	1,680
Pool Pavilion	2009	22-23	10	0	0	3,420 Square Feet	1.80	6,156
Resident's Club	2009	22-23	10	0	0	6,200 Square Feet	1.80	11,160

Rolling Hills CDD Component Inventory

		a d	gent.		agai.	is Sec		~
Description	Oge Ser	555 76	gent User	d dij	San Sala	Side Side	Jak Cost	CHI COS
Exterior Painting continued								
Tennis Pavilion	2009	22-23	10	0	0	1 Lump Sum	1,680.00	1,680
Exterior Painting - Total								\$20,676
Flooring								
Carpet - Resident's Club Great Room	2009	23-24	12	3	1	46 Square Yards	37.40	1,720
Carpet - Resident's Club Offices	2009	23-24	12	3	1	48 Square Yards	37.40	1,795
Floor Tile - 1st Floor	2009	38-39	30	0	16	432 Square Feet	1.30	562
Floor Tile - Lobby	2009	38-39	30	0	16	340 Square Feet	12.30	4,182
Rubber Flooring - Fitness Room	2009	33-34	25	0	11	56 Square Yards	40.00	2,240
Vinyl Flooring - Kids Zone	2009	33-34	25	0	11	780 Square Feet	6.00	4,680
Flooring - Total								\$15,179
Cabinets & Tops								
Top/Sink - Pavilion	2009	33-34	25	0	11	1 Each	1,000.00	1,000
Wood Cabinets & SS Tops - Kitchen	2009	28-29	20	0	6	18 Lineal Feet	173.00	3,114
Wood Cabinets & SS Tops - Reception/Conf	2009	28-29	20	0	6	31 Lineal Feet	173.00	_5,363
Cabinets & Tops - Total								\$9,477
Furniture Fixtures & Equipment								
Appliance Package - Kitchen	2009	25-26	12	5	3	1 Lump Sum	4,000.00	4,000
Fitness Equip. Full Replace Allowance	2009	36-37	25	3	14	1 Lump Sum	25,000.00	25,000
Furniture Allowance - Resident's Club	2009	28-29	20	0	6	1 Lump Sum	5,000.00	5,000
Pool/Deck Furniture Full Replacement Allo.		30-31	22	0	8	1 Lump Sum	30,000.00	30,000
Wall Oven Double	2009	25-26	12	5	3	1 Each	1,960.00	1,960
Furniture Fixtures & Equipment - Total							-,,	\$65,960
HVAC Equipment								
HVAC Equipment	2000	22.24	12	2	1	1 Eash	16,000,00	16,000
Heat Pump 1 - 10 Ton	2009 2009	23-24 23-24	12 12	3	1	1 Each	16,000.00	16,000
Heat Pump 2 - 8 Ton Heat Pump 3 - 7 Ton	2009	23-24	12	3	1 1	1 Each 1 Each	12,800.00 11,200.00	12,800
HVAC Equipment - Total	2009	23-24	12	3	1	I Lacii	11,200.00	\$40,000
Trac Equipment - Total								ψ -1 0,000
Swimming Pool								
Concrete Pavers - Pool	2009	38-39	30	0	16	19,327 Square Feet	8.10	156,549
Fiberglass Refurbishment Allow - Pool Slide	2009	23-24	12	3	1	1 Lump Sum	15,000.00	15,000
Lane Divider Reel	2009	38-39	30	0	16	1 Each	2,100.00	2,100
Lane Dividers	2009	23-24	12	3	1	6 Lanes	530.00	3,180
Play Equip. Refurbishment Allow - Splash P	2009	23-24	12	3	1	1 Lump Sum	5,000.00	5,000
Pool Filtration Refurbishment Allowance	2007	36-37	30	0	14	1 Lump Sum	40,000.00	40,000
Pool Lift	2009	28-29	20	0	6	2 Each	3,200.00	6,400
Pool Resurfacing/Tile Misc Repair	2009	23-24	12	3	1	11,200 Square Feet	26.80	300,160
Shade Structure Fabric - Pool	2009	23-24	12	3	1	5 Each	2,400.00	12,000
Shade Structure Frame - Pool	2009	33-34	25	0	11	5 Each	6,800.00	34,000
Starting Blocks	2009	28-29	20	0	6	6 Each	2,700.00	16,200

Rolling Hills CDD Component Inventory

	•	م څ	jeni.		aea .	into		\$
Description	Ope Sol	50 76 76	ولا من الم	ş _{dil} i	Stantist .	Jith	Jätost	CHI COS
Swimming Pool continued Steel Stair Refurbishment Allowance Swimming Pool - Total	2009	33-34	25	0	11	1 Lump Sum	15,000.00	15,000 \$605,589
Tennis Courts								
Asphalt Resufacing (color coat)	2016	23-24	7	1	1	4,684 Square Yards	8.20	38,409
Shade Structure Frame - Tennis Courts Tennis Courts - Total	2009	33-34	25	0	11	3 Each	3,200.00	<u>9,600</u> \$48,009
Playground								
Park Bench Expanded Metal	2009	28-29	20	0	6	2 Each	1,300.00	2,600
Plastic Play Surface Border	2009	28-29	20	0	6	246 Lineal Feet	21.00	5,166
Play Equipment Allowance	2009	28-29	15	5	6	1 Lump Sum	30,000.00	30,000
Swings Two Bay Arched Playground - Total	2009	28-29	15	5	6	1 Each	3,200.00	3,200 \$40,966
Components Not Included								

Components Not Included Asphalt Seal Coat

Asphalt Seal Coat	Unfunded
Building Sign	Unfunded
Ceiling Fans	Unfunded
Community Signs	Unfunded
Concrete Curbs/Walks	Unfunded
Doors/Windows	Unfunded
Dumpster Enclosure/Gates	Unfunded
Electric Lift	Unfunded
Fitness Equipment Partial Replace Allowance	Unfunded
Flag Pole	Unfunded
Gas Grill	Unfunded
Irrigation System	Unfunded
Landscaping	Unfunded
Light Poles - Parking Lot	Unfunded
Monument Sign Refurbishment	Unfunded
Nets/Poles - Tennis Courts	Unfunded
Pond Fountains/Aerators	Unfunded
Pool Filtration Partial Replacement	Unfunded
Pool/Deck Furniture Partial Replacement	Unfunded
Railings	Unfunded
Rubber Play Surface - Playground	Unfunded
Shade Structure Fabric - Tennis Courts	Unfunded
Stormwater Pond Dredging/Pipe/Structures	Unfunded
Tennis Court Replacement	Unfunded
Utility Lines	Unfunded
Volley Ball Court	Unfunded
Water Cooler - Tennis Courts	Unfunded
Water Coolers	Unfunded
Components Not Included - Total	

Total Asset Summary \$1,407,847

Asset II	DDescription	Replacement	Page
Misc. S	Site Components		
1073	Concrete Pavers - Entry	33-34	5-8
1003	Concrete Pavers - Resident's Club	38-39	5-8
1077	Mail Box Pedestals	44-45	5-9
1075	Street Signs/Poles	38-39	5-9
1094	Wood Boardwalk Frame/Rails/Deck (not pilings)	33-34	5-10
Parkin	g Lot Resurfacing		
1067	Asphalt Mill/Overlay 1 1/2" - Parking Lot	30-31	5-11
Site Li	ghting		
1031	Decorative Light Poles - Amenity	32-33	5-12
1059	Light Poles Shoebox Fixtures - Tennis Courts	32-33	5-12
Fencin	g		
1029	Aluminum Fence - Pool	38-39	5-13
1057	Chain Link Fence VC 10 Ft - Tennis Courts	32-33	5-13
Misc. F	Building Components		
1018	Aluminum Gutters/DS - Resident's Club & Pavilion	38-39	5-14
1013	Refurbishment Allowance - Family Restroom	28-29	5-14
1012	Refurbishment Allowance - Fitness Locker Rooms	28-29	5-15
1054	Refurbishment Allowance - Pavilion Restrooms	28-29	5-15
1028	Refurbishment Allowance - Pool Restrooms	28-29	5-16
1019	Vinyl Railings - Porch	38-39	5-16
1020	Wood Deck - Porch	28-29	5-17
Roofin	g		
1051	Asphalt Shingles - Pavilion	38-39	5-18
1001	Asphalt Shingles - Resident's Club	38-39	5-18
1095	Metal Roof - Picnic Pavilion	38-39	5-19
1026	Metal Roof - Pool Monitor	38-39	5-19
1091	Metal Roof - Resident's Club	38-39	5-20
1063	Metal Roof - Tennis Pavilion	38-39	5-20
Exterio	or Painting		
1096	Picnic Pavilion	22-23	5-21
1066	Pool Pavilion	22-23	5-21

Asset ID Description		Replacement	Page	
Exterior Painting Continued				
1092	Resident's Club	22-23	5-22	
1065	Tennis Pavilion	22-23	5-22	
Floorii	ng			
1014	Carpet - Resident's Club Great Room	23-24	5-23	
1006	Carpet - Resident's Club Offices	23-24	5-23	
1102	Floor Tile - 1st Floor	38-39	5-24	
1009	Floor Tile - Lobby	38-39	5-24	
1010	Rubber Flooring - Fitness Room	33-34	5-25	
1103	Vinyl Flooring - Kids Zone	33-34	5-26	
Cabine	ets & Tops			
1053	Top/Sink - Pavilion	33-34	5-27	
1015	Wood Cabinets & SS Tops - Kitchen	28-29	5-27	
1007	Wood Cabinets & SS Tops - Reception/Conf. Rm	28-29	5-28	
	ure Fixtures & Equipment	25.26	7.2 0	
1017	Appliance Package - Kitchen	25-26	5-29	
1106	Fitness Equip. Full Replace Allowance	36-37	5-29	
1016	Furniture Allowance - Resident's Club	28-29	5-30	
1039	Pool/Deck Furniture Full Replacement Allowance	30-31	5-31	
1025	Wall Oven Double	25-26	5-31	
HVAC	Equipment			
1105	Heat Pump 1 - 10 Ton	23-24	5-32	
1104	Heat Pump 2 - 8 Ton	23-24	5-32	
1023	Heat Pump 3 - 7 Ton	23-24	5-32	
~ .				
	ning Pool	•••		
1030	Concrete Pavers - Pool	38-39	5-33	
1036	Fiberglass Refurbishment Allow - Pool Slide	23-24	5-33	
1055	Lane Divider Reel	38-39	5-34	
1056	Lane Dividers	23-24	5-34	
1043	Play Equip. Refurbishment Allow - Splash Pool	23-24	5-35	
1107	Pool Filtration Refurbishment Allowance	36-37	5-35	
1042	Pool Lift	28-29	5-35	
1032	Pool Resurfacing/Tile Misc Repair	23-24	5-36	

Asset I	DDescription	Replacement	Page	
Swimming Pool Continued				
1035	Shade Structure Fabric - Pool	23-24	5-37	
1033	Shade Structure Frame - Pool	33-34	5-37	
1037	Starting Blocks	28-29	5-38	
1040	Steel Stair Refurbishment Allowance	33-34	5-38	
10.0	Steel Stail Relate Shimele Line Wante	33 3 1	2 20	
Tennis	Courts			
1058	Asphalt Resufacing (color coat)	23-24	5-39	
1060	Shade Structure Frame - Tennis Courts	33-34	5-39	
Playgre	ound			
1049	Park Bench Expanded Metal	28-29	5-41	
1046	Plastic Play Surface Border	28-29	5-41	
1044	Play Equipment Allowance	28-29	5-42	
1048	Swings Two Bay Arched	28-29	5-42	
~				
_	onents Not Included	22.22	7 40	
1068	Asphalt Seal Coat	22-23	5-43	
1005	Building Sign	22-23	5-43	
1021	Ceiling Fans	22-23	5-44	
1078	Community Signs	22-23	5-44	
1071	Concrete Curbs/Walks	22-23	5-45	
1022	Doors/Windows	22-23	5-45	
1069	Dumpster Enclosure/Gates	22-23	5-45	
1008	Electric Lift	22-23	5-46	
1011	Fitness Equipment Partial Replace Allowance	22-23	5-46	
1002	Flag Pole	22-23	5-47	
1052	Gas Grill	22-23	5-47	
1099	Irrigation System	22-23	5-48	
1100	Landscaping	22-23	5-48	
1070	Light Poles - Parking Lot	22-23	5-48	
1074	Monument Sign Refurbishment	22-23	5-49	
1064	Nets/Poles - Tennis Courts	22-23	5-49	
1101	Pond Fountains/Aerators	22-23	5-50	
1108	Pool Filtration Partial Replacement	22-23	5-50	
1038	Pool/Deck Furniture Partial Replacement	22-23	5-50	
1004	Railings	22-23	5-51	
1047	Rubber Play Surface - Playground	22-23	5-51	

Asset ID Description		Replacement	Page
Compo	nents Not Included Continued		
1061	Shade Structure Fabric - Tennis Courts	22-23	5-52
1076	Stormwater Pond Dredging/Pipe/Structures	22-23	5-52
1045	Tennis Court Replacement	22-23	5-53
1098	Utility Lines	22-23	5-53
1050	Volley Ball Court	22-23	5-54
1062	Water Cooler - Tennis Courts	22-23	5-54
1027	Water Coolers	22-23	5-55
	Total Funded Assets	62	
	Total Unfunded Assets	<u>28</u>	
	Total Assets	90	

Concrete Pavers - Entry - 2033

Asset ID 1073

 1,560 Square Feet
 @ \$8.10

 Asset Actual Cost
 \$12,636.00

 Percent Replacement
 100%

 Future Cost
 \$18,528.31

Misc. Site Components
Placed in Service January 2009
Useful Life 25

Useful Life 25
Replacement Year 33-34
Remaining Life 11



Concrete Pavers - Resident's Club - 2038

Asset ID 1003

1,029 Square Feet @ \$8.10 Asset Actual Cost \$8,334.90 Percent Replacement 100% Future Cost \$14,168.14

Misc. Site Components
Placed in Service January 2009
Useful Life 30
Replacement Year 38-39
Remaining Life 16



Mail Box Pedestals - 2044

Asset ID 1077

Misc. Site Components

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
January 2020
44-45
22



Street Signs/Poles - 2038

Asset ID 1075

Misc. Site Components e January 2009

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
January 2009
38-39
16



Wood Boardwalk Frame/Rails/Deck (not pilings) - 2033

 Asset ID
 1094
 2,280 Square Feet Asset Actual Cost Percent Replacement Future Cost
 \$72,960.00 \$72,960

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
January 2009
33-34
11



Asphalt Mill/Overlay 1 1/2" - Parking Lot - 2030

Asset ID 1067 Square Yards @ \$17.20
Asset Actual Cost \$96,715.60
Percent Replacement 100%
Parking Lot Resurfacing Future Cost \$129,781.01

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2009

30-31

8



Decorative Light Poles - Amenity - 2032

Asset ID 1031

16 Each @ \$2,100.00
Asset Actual Cost \$33,600.00
Percent Replacement 100%
Future Cost \$47,833.08

Placed in Service January 2009
Useful Life 24
Replacement Year 32-33
Remaining Life 10



Light Poles Shoebox Fixtures - Tennis Courts - 2032

Asset ID 1059 Asset Actual Cost \$64,800.00
Percent Replacement 100%
Site Lighting Future Cost \$92,249.51

Placed in Service January 2009
Useful Life 24
Replacement Year 32-33
Remaining Life 10



Aluminum Fence - Pool - 2038

Asset ID 1029

790 Lineal Feet @ \$36.00 Asset Actual Cost \$28,440.00 Percent Replacement 100% Future Cost \$48,343.94

Placed in Service January 2009
Useful Life 30
Replacement Year 38-39
Remaining Life 16



Chain Link Fence VC 10 Ft - Tennis Courts - 2032

1,386 Lineal Feet @ \$33.60
Asset ID 1057 Asset Actual Cost \$46,569.60

Percent Replacement 100% Fencing Future Cost \$66,296.65

Placed in Service January 2009
Useful Life 24
Replacement Year 32-33
Remaining Life 10




Aluminum Gutters/DS - Resident's Club & Pavilion - 2038

Asset ID 1018 Asset Actual Cost \$3,728.60
Percent Replacement 100%
Misc. Building Components Future Cost \$6,338.09

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
January 2009
38-39
16





Refurbishment Allowance - Family Restroom - 2028

2 Each @ \$2,600.00
Asset ID 1013 Asset Actual Cost \$5,200.00
Percent Replacement 100%
Misc. Building Components Future Cost \$6,577.24

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2009
28-29
6



Community Advisors Page 5-14 May 25, 2022

Refurbishment Allowance - Fitness Locker Rooms - 2028

Asset ID 1012 Asset Actual Cost \$20,400.00
Percent Replacement 100%
Misc. Building Components Future Cost \$25,803.01

Placed in Service
Useful Life
Replacement Year
Remaining Life
January 2009
28-29
Remaining Life
G





Refurbishment Allowance - Pavilion Restrooms - 2028

Asset ID 1054 Asset Actual Cost \$17,408.00
Percent Replacement 100%
Misc. Building Components Future Cost \$22,018.57

Placed in Service January 2009
Useful Life 20
Replacement Year 28-29
Remaining Life 6



Community Advisors Page 5-15 May 25, 2022

Refurbishment Allowance - Pool Restrooms - 2028

Asset ID 1028 Asset Actual Cost \$36,040.00
Percent Replacement 100%
Misc. Building Components Future Cost \$45,585.31

Placed in Service
Useful Life
Replacement Year
Remaining Life
January 2009
28-29
Remaining Life
G





Vinyl Railings - Porch - 2038

Remaining Life

Asset ID 1019

Misc. Building Components
Placed in Service January 2009
Useful Life 30
Replacement Year 38-39

49 Lineal Feet @ \$55.00 Asset Actual Cost \$2,695.00 Percent Replacement 100% Future Cost \$4,581.11



16

Wood Deck - Porch - 2028

 Asset ID
 1020
 Asset Actual Cost Percent Replacement
 \$1,736.00

 Misc. Building Components
 Future Cost
 \$2,195.79

Placed in Service January 2009
Useful Life 20
Replacement Year 28-29
Remaining Life 6



Asphalt Shingles - Pavilion - 2038

Asset ID 1051

41 Squares @ \$480.00 **Asset Actual Cost** \$19,680.00 Percent Replacement 100% Future Cost \$33,453.19

@ \$484.00

Roofing January 2009 Placed in Service Useful Life 30 Replacement Year 38-39 Remaining Life 16



Asphalt Shingles - Resident's Club - 2038

96 Squares Asset ID 1001 **Asset Actual Cost** \$46,464.00 Percent Replacement 100% **Future Cost** \$78,982.16

Roofing January 2009 Placed in Service Useful Life 30 Replacement Year 38-39 Remaining Life 16





Metal Roof - Picnic Pavilion - 2038

		452 Square Feet	@ \$8.20
Asset ID	1095	Asset Actual Cost	\$3,706.40
		Percent Replacement	100%
	Roofing	Future Cost	\$6,300.35
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	38-39		
Remaining Life	16		



Metal Roof - Pool Monitor - 2038

Placed in Service

Asset ID 1026

Roofing January 2009 30

Useful Life 30
Replacement Year 38-39
Remaining Life 16

190 Square Feet @ \$8.20 Asset Actual Cost \$1,558.00 Percent Replacement 100% Future Cost \$2,648.38



Metal Roof - Resident's Club - 2038

		714 Square Feet	@ \$8.20
Asset ID	1091	Asset Actual Cost	\$5,854.80
		Percent Replacement	100%
	Roofing	Future Cost	\$9,952.32
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	38-39		
Remaining Life	16		



Metal Roof - Tennis Pavilion - 2038

Asset ID	1063	520 Square Feet Asset Actual Cost Percent Replacement	@ \$8.20 \$4,264.00 100%
	Roofing	Future Cost	\$7,248.19
Placed in Service	January 2009		
Useful Life	30		
Replacement Year	38-39		
Remaining Life	16		



Community Advisors Page 5-20 May 25, 2022

Picnic Pavilion - 2022

Asset ID 1096

1 Lump Sum
Asset Actual Cost
Percent Replacement
Future Cost

@ \$1,680.00 \$1,680.00 100% \$1,680.00

Placed in Service January 2009
Useful Life 10
Replacement Year Remaining Life 22-23



Pool Pavilion - 2022

Asset ID

1066

3,420 Square Feet Asset Actual Cost Percent Replacement Future Cost @ \$1.80
\$6,156.00
100%
\$6,156.00

Placed in Service Ja
Useful Life
Replacement Year
Remaining Life

Exterior Painting January 2009 10 22-23 0



Resident's Club - 2022

Asset ID 1092

6,200 Square Feet @ \$1.80 Asset Actual Cost \$11,160.00 Percent Replacement 100% Future Cost \$11,160.00

Placed in Service January 2009
Useful Life 10
Replacement Year Remaining Life 22-23



Tennis Pavilion - 2022

Asset ID

1065

1 Lump Sum Asset Actual Cost Percent Replacement Future Cost @ \$1,680.00 \$1,680.00 100% \$1,680.00

Placed in Service January 2009
Useful Life 10
Replacement Year Remaining Life 22-23



Carpet - Resident's Club Great Room - 2023

		46 Square Yards	@ \$37.40
Asset ID	1014	Asset Actual Cost	\$1,720.40
		Percent Replacement	100%
	Flooring	Future Cost	\$1,823.62
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		



Carpet - Resident's Club Offices - 2023

		48 Square Yards	@ \$37.40
Asset ID	1006	Asset Actual Cost	\$1,795.20
		Percent Replacement	100%
	Flooring	Future Cost	\$1,902.91
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		

Carpet - Resident's Club Offices continued...





Floor Tile - 1st Floor - 2038

Asset ID 1102

432 Square Feet @ \$1.30 Asset Actual Cost \$561.60 Percent Replacement 100% Future Cost \$954.64

Placed in Service January 2009
Useful Life 30
Replacement Year 38-39
Remaining Life 16



Floor Tile - Lobby - 2038

Asset ID 1009 Asset Actual Cost \$4,182.00
Percent Replacement 100%
Flooring Future Cost \$7,108.80

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
January 2009
38-39
16

Community Advisors Page 5-24 May 25, 2022

Floor Tile - Lobby continued...



Rubber Flooring - Fitness Room - 2033

Asset ID	1010	56 Square Yards Asset Actual Cost Percent Replacement	@ \$40.00 \$2,240.00 100%
	Flooring	Future Cost	\$3,284.54
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	33-34		
Remaining Life	11		



Vinyl Flooring - Kids Zone - 2033

Asset ID 1103

780 Square Feet @ \$6.00 Asset Actual Cost \$4,680.00 Percent Replacement 100% Future Cost \$6,862.34

Placed in Service January 2009
Useful Life 25
Replacement Year 33-34
Remaining Life 11



Top/Sink - Pavilion - 2033

Asset ID 1053

@ \$1,000.00 1 Each **Asset Actual Cost** \$1,000.00 Percent Replacement Future Cost \$1,466.31

100%

Cabinets & Tops Placed in Service January 2009 Useful Life 25 Replacement Year 33-34 Remaining Life 11



Wood Cabinets & SS Tops - Kitchen - 2028

Asset ID 1015

18 Lineal Feet @ \$173.00 Asset Actual Cost \$3,114.00 Percent Replacement 100% **Future Cost** \$3,938.75

Cabinets & Tops Placed in Service January 2009 Useful Life 20 Replacement Year 28-29 Remaining Life 6



Wood Cabinets & SS Tops - Reception/Conf. Rm - 2028

Asset ID 1007 Asset Actual Cost \$5,363.00
Percent Replacement 100%
Cabinets & Tops Future Cost \$6,783.41

Placed in Service January 2009
Useful Life 20
Replacement Year 28-29
Remaining Life 6





Appliance Package - Kitchen - 2025

		1 Lump Sum	@ \$4,000.00
Asset ID	1017	Asset Actual Cost	\$4,000.00
		Percent Replacement	100%
Furniture Fixtures & Equipment		Future Cost	\$4,630.08
Placed in Service	January 2009		
Useful Life	12		
Adjustment	5		
Replacement Year	25-26		
Remaining Life	3		



Fitness Equip. Full Replace Allowance - 2036

		1 Lump Sum	@ \$25,000.00
Asset ID	1106	Asset Actual Cost	\$25,000.00
		Percent Replacement	100%
Furniture Fixtures & Equipment		Future Cost	\$40,056.96
Placed in Service	January 2009		
Useful Life	25		
Adjustment	3		
Replacement Year	36-37		
Remaining Life	14		

Fitness Equip. Full Replace Allowance continued...



Furniture Allowance - Resident's Club - 2028

		1 Lump Sum	@ \$5,000.00
Asset ID	1016	Asset Actual Cost	\$5,000.00
		Percent Replacement	100%
Furniture Fixtures & Equipment		Future Cost	\$6,324.27

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2009
28-29
6



Pool/Deck Furniture Full Replacement Allowance - 2030

1 Lump Sum @ \$30,000.00
Asset ID 1039 Asset Actual Cost \$30,000.00
Percent Replacement 100%
Furniture Fixtures & Equipment Future Cost \$40,256.49

Placed in Service
Useful Life
Replacement Year
Remaining Life
January 2009
30-31
8






Wall Oven Double - 2025

Asset ID 1025 Asset Actual Cost \$1,960.

Percent Replacement 100

Furniture Fixtures & Equipment
Placed in Service January 2009
Useful Life 12
Adjustment 5
Replacement Year 25-26
Remaining Life 3





Heat Pump 1 - 10 Tor	n - 2023	1 Each	@ \$16,000.00
Asset ID	1105	Asset Actual Cost	\$16,000.00
		Percent Replacement	100%
	HVAC Equipment	Future Cost	\$16,960.00
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		
Heat Pump 2 - 8 Ton	- 2023	1 Each	@ \$12,800.00
Asset ID	1104	Asset Actual Cost	\$12,800.00
		Percent Replacement	100%
	HVAC Equipment	Future Cost	\$13,568.00
Placed in Service	January 2009		ŕ
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		
H + D 2 7 T	2022		
Heat Pump 3 - 7 Ton	- 2023	1 Each	@ \$11,200.00
Asset ID	1023	Asset Actual Cost	\$11,200.00
		Percent Replacement	100%
	HVAC Equipment	Future Cost	\$11,872.00
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		

Concrete Pavers - Pool - 2038

Asset ID 1030

Placed in Service January 2009
Useful Life 30
Replacement Year Remaining Life 16



Fiberglass Refurbishment Allow - Pool Slide - 2023

Asset ID 1036 Asset Actual Cost \$15,000.00

Percent Replacement 100%

Swimming Pool Future Cost \$15,900.00

Placed in Service January 2009
Useful Life 12
Adjustment 3
Replacement Year 23-24
Remaining Life 1





Lane Divider Reel - 2038

Asset ID 1055

Placed in Service January 2009
Useful Life 30
Replacement Year Remaining Life 16



Lane Dividers - 2023

Asset ID 1056

6 Lanes @ \$530.00
Asset Actual Cost \$3,180.00
Percent Replacement 100%
Future Cost \$3,370.80

Placed in Service
Useful Life
Adjustment
Adjustment
Replacement Year
Remaining Life
Swimming Pool
January 2009
23-24
Swimming Pool
January 2009
12
23-24



Play Equip. Refurbishment Allow - Splash Pool - 2023

Asset ID	1043	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$5,000.00 \$5,000.00 100%
	Swimming Pool	Future Cost	\$5,300.00
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		



Pool Filtration Refurbishment Allowance - 2036

Asset ID	1107 Swimming Pool	1 Lump Sum Asset Actual Cost Percent Replacement Future Cost	<pre>@ \$40,000.00 \$40,000.00 100% \$64,091.14</pre>
Placed in Service	January 2007		. ,
Useful Life	30		
Replacement Year	36-37		
Remaining Life	14		
Pool Lift - 2028		2 Each	@ \$3,200.00
Asset ID	1042	Asset Actual Cost	\$6,400.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$8,095.06
Placed in Service	January 2009		
Useful Life	20		
Replacement Year	28-29		
Remaining Life	6		

Community Advisors Page 5-35 May 25, 2022

Pool Lift continued...





Pool Resurfacing/Tile Misc Repair - 2023

		11,200 Square Feet	@ \$26.80
Asset ID	1032	Asset Actual Cost	\$300,160.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$318,169.60
Placed in Service	January 2009		
Useful Life	12		
Adjustment	3		
Replacement Year	23-24		
Remaining Life	1		



Shade Structure Fabric - Pool - 2023

Remaining Life

Asset ID 1035

Placed in Service January 2009
Useful Life 12
Adjustment 3
Replacement Year 23-24



1

Shade Structure Frame - Pool - 2033

Asset ID 1033

Placed in Service
Useful Life
Replacement Year
Remaining Life
Swimming Pool
January 2009
33-34
11



Starting Blocks - 2028

Asset ID 1037 Asset Actual Cost \$16,200.00
Percent Replacement 100%
Swimming Pool Future Cost \$20,490.62

Placed in Service January 2009
Useful Life 20
Replacement Year 28-29
Remaining Life 6



Steel Stair Refurbishment Allowance - 2033

Asset ID 1040 Asset Actual Cost \$15,000.00

Percent Replacement 100%

Swimming Pool Future Cost \$21,994.68

Placed in Service January 2009
Useful Life 25
Replacement Year 33-34
Remaining Life 11



Asphalt Resufacing (color coat) - 2023

		4,684 Square Yards	@ \$8.20
Asset ID	1058	Asset Actual Cost	\$38,408.80
		Percent Replacement	100%
	Tennis Courts	Future Cost	\$40,713.33
Placed in Service	January 2016		
Useful Life	7		
Adjustment	1		
Replacement Year	23-24		
Remaining Life	1		



Shade Structure Frame - Tennis Courts - 2033

Asset ID	1060	3 Each Asset Actual Cost Percent Replacement	@ \$3,200.00 \$9,600.00 100%
	Tennis Courts	Future Cost	\$14,076.59
Placed in Service	January 2009		
Useful Life	25		
Replacement Year	33-34		
Remaining Life	11		

Shade Structure Frame - Tennis Courts continued...



Park Bench Expanded Metal - 2028

Asset ID 1049

2 Each @ \$1,300.00
Asset Actual Cost \$2,600.00
Percent Replacement Future Cost \$3,288.62

Playground
Placed in Service
Useful Life
Replacement Year
Remaining Life
Playground
January 2009
28-29
Replacement Year
Remaining Life



Plastic Play Surface Border - 2028

Asset ID 1046

246 Lineal Feet @ \$21.00 Asset Actual Cost \$5,166.00 Percent Replacement 100% Future Cost \$6,534.23

Playground
Placed in Service
Useful Life
Replacement Year
Remaining Life
Playground
January 2009
28-29
6



Play Equipment Allowance - 2028

 nent Allowance - 2028
 1 Lump Sum
 @ \$30,000.00

 Asset ID
 1044
 Asset Actual Cost
 \$30,000.00

 Percent Replacement
 100%

 Playground
 Future Cost
 \$37,945.60

Placed in Service January 2009
Useful Life 15
Adjustment 5
Replacement Year 28-29
Remaining Life 6



Swings Two Bay Arched - 2028

Asset ID 1048 Asset Actual Cost \$3,200.00 Percent Replacement 100%

1 Each

Future Cost

@ \$3,200.00

\$4,047.53



Community Advisors Page 5-42 May 25, 2022

Asphalt Seal Coat

Asset ID 1068 Asset Actual Cost

Percent Replacement
Components Not Included Future Cost

100%

Placed in Service January 2009 No Useful Life

No Useful Life



Building Sign

Asset ID 1005 Asset Actual Cost
Percent Replacement 100%
Components Not Included Future Cost

Components Not Included
Placed in Service January 2009
No Useful Life

ary 2009



Ceiling Fans

Asset ID 1021

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included

Placed in Service No Useful Life January 2009



Community Signs

Asset ID 1078

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included Placed in Service January 2009

No Useful Life



Concrete Curbs/Walks

Asset ID 1071

Asset Actual Cost Percent Replacement

Future Cost

100%

Components Not Included

Placed in Service No Useful Life January 2009



Doors/Windows

Asset ID

1022

Asset Actual Cost

Percent Replacement **Future Cost** 100%

Components Not Included Placed in Service January 2009

No Useful Life

Dumpster Enclosure/Gates

Asset ID 1069 Asset Actual Cost

Components Not Included

Percent Replacement

Future Cost

100%

Placed in Service No Useful Life January 2009

Community Advisors Page 5-45

Dumpster Enclosure/Gates continued...



Electric Lift

Asset ID 1008

Components Not Included
Placed in Service January 2009
No Useful Life

Asset Actual Cost
Percent Replacement
Future Cost

100%



Fitness Equipment Partial Replace Allowance

Asset ID 1011

Components Not Included vice January 2009

Asset Actual Cost Percent Replacement Future Cost

100%

No Useful Life

Placed in Service

Community Advisors Page 5-46 May 25, 2022

Fitness Equipment Partial Replace Allowance continued...



Flag Pole

Asset ID 1002

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Gas Grill

Asset ID 1052

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included
Placed in Service January 2009
No Useful Life

Community Advisors Page 5-47 May 25, 2022

Gas Grill continued...



Irrigation System

1099 Asset ID

100%

Components Not Included Placed in Service January 2009

No Useful Life

Asset Actual Cost Percent Replacement **Future Cost**

Landscaping

Asset ID 1100

Asset Actual Cost Percent Replacement

Future Cost

100%

Components Not Included Placed in Service January 2009

No Useful Life

Light Poles - Parking Lot

Asset ID 1070 Asset Actual Cost

Percent Replacement Components Not Included January 2009

Placed in Service

No Useful Life

Future Cost

100%

Light Poles - Parking Lot continued...



Monument Sign Refurbishment

Asset ID 1074

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost
Percent Replacement
Future Cost

100%



Nets/Poles - Tennis Courts

Asset ID 1064

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included
Placed in Service January 2009
No Useful Life

Community Advisors Page 5-49 May 25, 2022

Nets/Poles - Tennis Courts continued...



Pond Fountains/Aerators

Asset ID 1101

Components Not Included
Placed in Service January 2009
No Useful Life

Asset Actual Cost
Percent Replacement 100%
Future Cost

100%

100%

Pool Filtration Partial Replacement

Asset ID 1108 Asset Actual Cost Percent Replacement

Components Not Included
Placed in Service January 2007
No Useful Life

omponents Not Included Future Cost
January 2007

Pool/Deck Furniture Partial Replacement

Asset ID 1038 Asset Actual Cost

Components Not Included
Placed in Service January 2009
No Useful Life

Percent Replacement
Future Cost

Pool/Deck Furniture Partial Replacement continued...





Railings

Asset ID 1004

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Rubber Play Surface - Playground

Asset ID 1047

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%

Rubber Play Surface - Playground continued...



Shade Structure Fabric - Tennis Courts

Asset ID 1061

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost
Percent Replacement
Future Cost



Stormwater Pond Dredging/Pipe/Structures

Asset ID 1076

Components Not Included Placed in Service January 2009 No Useful Life Asset Actual Cost
Percent Replacement
Future Cost

Stormwater Pond Dredging/Pipe/Structures continued...



Tennis Court Replacement

No Useful Life

Asset ID 1045

Components Not Included January 2009 Placed in Service

Asset Actual Cost Percent Replacement **Future Cost**

100%



Utility Lines

Asset ID

Asset Actual Cost Percent Replacement **Future Cost**

100%

Components Not Included Placed in Service No Useful Life

January 2009

1098

Community Advisors Page 5-53 May 25, 2022

Volley Ball Court

Asset ID 1050

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included Placed in Service January 2009

No Useful Life



Water Cooler - Tennis Courts

Asset ID

1062

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included
Placed in Service January 2009
No Useful Life





Water Coolers

Asset ID 1027

Asset Actual Cost Percent Replacement Future Cost

100%

Components Not Included Placed in Service January 2009 No Useful Life



Report Navigation

- **Executive Summary** provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Component Funding or Pooled Cash
 - Component Funding Contribution is a year one only amount
 - Current Funding Plan currently used by the Association
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- Cash Flow is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- **Annual Expenditure Detail** provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- Component Detail Index allows quick access to the detail we have included for each component separated into categories
- Component Detail provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the Association can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors, and comparison of similar component cost found at other properties.

The funding plan we develop includes adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. <u>Full Funding</u> provides the best option to avoid deferred maintenance or special assessments. <u>Baseline Funding</u> maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums, and commercial investment properties.

Personal Service attention to detail, quick response, and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street, and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.